



CHARLES CENTER • P. O. BOX 1475 • BALTIMORE, MARYLAND 21203

ARTHUR E. LUNDVALL, JR.
VICE PRESIDENT
SUPPLY

July 30, 1984

U. S. Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, PA 19406

Docket Nos. 50-317
50-318
License Nos. DPR-53
DPR-69

ATTENTION: Mr. R. W. Starostecki, Director
Division Project & Resident
Programs

Gentlemen:

This refers to Inspection Report 50-317/84-11, 50-318/84-11; which transmitted one item of apparent noncompliance with NRC requirements. Enclosure (1) to this letter is a written statement in reply to that item noted in your letter of July 3, 1984.

Should you have further questions regarding this reply, we will be pleased to discuss them with you.

Very truly yours,

AEL/LOW/gla

Enclosure

cc: D. A. Brune, Esquire
G. F. Trowbridge, Esquire
D. H. Jaffe, NRC
T. Foley, NRC

8410230328 840730
PDR ADOCK 05000317
Q PDR

11
1E01

ENCLOSURE (1)

**REPLY TO APPENDIX A OF NRC INSPECTION
REPORT 50-317/84-11; 50-318/84-11**

We have reviewed the circumstances that led to the apparent violation of 10 CFR 50, Appendix B, Criterion XVI requiring timely corrective action to assure that conditions such as improper valve labeling of the Hydrogen Analyzers are properly identified and corrected. The root cause leading to this event was a failure to fully implement corrective action in a manner that would have prevented an apparent violation of valve mislabeling in the Gas Analyzing System. Accordingly, the corrective actions cited below have been or will be implemented to ensure similar violations will not occur in the future.

- (1) A complete review of the Oxygen and Hydrogen Analyzing Cabinets has been performed and all valve labeling discrepancies identified. The discrepancies will be corrected through the on-going efforts of the Valve Labeling Program by September 1, 1984.
- (2) This incident was reviewed and discussed with Electrical & Controls Technicians to emphasize the impact of improper equipment labeling and the potential problems that can result. This action was completed on July 17, 1984.

OCT 0 9 1984

Enclosures:

1. Appendix A, Notice of Violation
2. NRC:RI Report 50-317/84-19, 50-318/84-19

cc w/enclosures:

R. M. Douglass, Manager, Quality Assurance
L. B. Russell, Plant Superintendent
S. M. Davis, General Supervisor, Operations QA
T. Magette, Administrator, Nuclear Evaluations
R. C. L. Olson, Principal Engineer, Nuclear Licensing & Analysis Unit
J. A. Tiernan, Manager, Nuclear Power Department
R. E. Denton, General Supervisor, Training and Technical Services
Public Document Room (PDR)
Local Public Document Room (LPDR)
Nuclear Safety Information Center (NSIC)
NRC Resident Inspector
State of Maryland (2)

bcc w/enclosures:

Region I Docket Room (with concurrences)
Senior Operations Officer (w/o enclosures)
Director, DETP
DPRP Section Chief