

RECEIVED  
NRC

Arizona Public Service Company

1984 JUL 23 PM 2:20

July 18, 1984  
ANPP-29988-TDS/TRB REGIONAL

U. S. Nuclear Regulatory Commission  
Region V  
Creskide Oaks Office Park  
1430 Maria Lane - Suite 210  
Walnut Creek, CA 94596-5368

Attention: Mr. T. W. Bishop, Director  
Division of Resident  
Reactor Projects and Engineering Programs

Subject: Deficiency Evaluation Report 84-43  
A 50.55(e) Evaluation Relating To HPSI 3" Gate Valve Failure  
To Open.  
File: 84-019-026; D.4.33.2


Reference: Telephone Conversation between P. Narbut and T. Bradish on  
June 22, 1984

Dear Sir:

The NRC was notified of the subject Deficiency Evaluation in the  
referenced telephone conversation, with a determination of reportability  
to be made within thirty (30) days (July 22, 1984).

The deficiency has subsequently been determined to be Not Reportable  
under the requirements of 10CFR50.55(e), therefore no written report is  
required. Necessary documentation of the evaluation will be maintained  
in APS files.

Very truly yours,



E. E. Van Brunt, Jr.  
APS Vice President  
Nuclear Production  
ANPP Project Director

EEVB/TRB:db

cc: See Page Two

8408010388 840718  
PDR ADOCK 05000528  
S PDR

1/0  
IE-27

Mr. T. W. Bishop  
DER 84-43  
Page Two

cc: Richard DeYoung, Director  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

T. G. Woods, Jr.  
D. B. Karner  
W. E. Ide  
D. B. Fasnacht  
A. C. Rogers  
L. A. Souza  
D. E. Fowler  
T. D. Shriver  
C. N. Russo  
J. Vorees  
J. R. Bynum  
J. M. Allen  
J. A. Brand  
A. C. Gehr  
W. J. Stubblefield  
W. G. Bingham  
R. L. Patterson  
R. W. Welcher  
H. D. Foster  
D. R. Hawkinson  
L. E. Vorderbrueggen  
R. P. Zimmerman  
S. R. Frost  
J. Self  
D. Canady  
T. J. Bloom

Records Center  
Institute of Nuclear Power Operations  
1100 Circle 75 Parkway, Suite 1500  
Atlanta, GA 30339