

July 31, 1984

W3P84-2062 3-A1.01.04 3-A19.09.09.03

Director of Nuclear Reactor Regulation Attention: Mr. G.W Knighton, Chief Licensing Branch No. 3 Division of Licensing U.S. Nuclear Regulatory Commission Washington, D.C. 20555

SUBJECT:

Waterford SES Unit 3 Docket No. 50-382

Revision to Procedures Generation Package

REFERENCES:

(1) Letter dated May 7, 1984

from Knighton (NRC) to Leddick (LP&L)

(2) Letter dated May 30, 1984

from Knighton (NRC) to Leddick (LP&L)

Dear Sir:

By your referenced letters you transmitted Staff comments on the Waterford 3 Procedures Generation Package (PGP) and requested that the PGP be revised to address those comments. As you requested, enclosed please find the revised PGP.

With this submittal LP&L has completed the requirements of NUREG 0737, Supplement 1 - Upgrade Emergency Operating Procedures, as well as the underlying guidance contained in NUREG 0737, specifically:

I.C.1 - Reanalysis of Transients and Accidents

I.C.7 - NSSS Vendor Review of Procedures

I.C.8 - Pilot Monitoring of Selected Emergency Operating Procedures

15.8 - Anticipated Transients Without Scram (procedure requirements)

We request that your review of this submittal and compliance with the above requirements be included in the next Supplement to the Waterford SER.



Should you require additional information in this matter please contact Mike Meisner at (504) 363-8938.

Yours very truly,

K.W. Cook

Nuclear Support & Licensing Manager

KWC/MJM/pco

Enclosures

cc: E.L. Blake, W.M. Stevenson, J.T. Collins, D.M. Crutchfield, J. Wilson, G.L. Constable, M. Goodman, J. Clifford