



ENTERGY

Entergy Operations, Inc.

PO Box 8
Waltham, MA 01906
Tel: 508 739 6774

R. F. Burski

Director
Document Control
Waltham, MA

W3F1-92-0118

A4 05

QA

February 12, 1992

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 20555

Subject: Waterford 3 SES
Docket No. 50-382
License No. NPF-38
Annual Environmental Operating Report - 1991

Dear Gentlemen:

Attached is the 1991 Annual Environmental Operating Report for the subject facility. This report is submitted pursuant to Section 5.4.1 of the Environmental Protection Plan (Appendix B to the Operating License).

Should you have any questions regarding this report, please contact A.R. Roberts at (504) 739-6326.

Very truly yours,

J. J. Zaitch for R.F. Burski

RFB/CJT/ssf
Attachment

cc: R.D. Martin, NRC Region IV
D.L. Wigginton, NRC-NRR
N.S. Reynolds
R.B. McGehee
M.O. Knudson, EPA
J.D. Givens, LA D&Q
NRC Resident Inspectors Office

100107

9202210253 911231
PDR ADOCK 05000382
R FDR

IE 25
11

1991 Annual Environmental Operating Report

This report describes implementation of the Environmental Protection Plan (EPP) for the calendar year 1991, and provides the information required by the EPP.

A. Summaries and analyses of the results of the environmental protection activities required by EPP subsection 4.2:

This section of the EPP provides protection of the two cultural resource areas on the Waterford 3 site. There were no activities which affected either the Plantation Overseer's House site or the Plantation Quarter's site, both eligible for the National Register of Historic Places, during this reporting period.

B. EPP noncompliances and the corrective actions taken to remedy them:

There were no noncompliances with the requirements of the EPP during this reporting period.

C. A discussion of changes in station design or operation, tests, or experiments made in accordance with the EPP subsection 3.1 which involved a potentially significant unreviewed environmental question:

There were no changes in station design, operation, tests, or experiments conducted that are reportable under this section during this reporting period. Though not involving a potentially significant unreviewed environmental question, it should be noted that NPDES Permit LA0007374 was renewed for a period of five years during this report period. Changes to the permit included the addition of two outfalls for stormwater runoff monitoring and the requirement for baseline biomonitoring of the effluent discharged through Outfall 001. Additionally, biomonitoring is required quarterly during periods of chlorination of the effluent discharged through Outfall 001.

D. Nonroutine reports submitted in accordance with subsection 5.4.2:

There were no nonroutine reports submitted in accordance with subsection 5.4.2 during this reporting period.