

Enclosure 1

SALP 9

FINAL SALP REPORT

U. S. NUCLEAR REGULATORY COMMISSION

REGION III

SYSTEMATIC ASSESSMENT OF LICENSEE PERFORMANCE

456/90001; 457/90001
Inspection Report Nos.

Commonwealth Edison Company
Name of Licensee

Braidwood Station, Units 1 and 2
Name of Facility

February 1, 1989 through January 31, 1990
Assessment Period

9511090120 900523
PDR ADOCK 05000456
Q PDR

9511090120

Braidwood Station

A. Summary of Meeting with Commonwealth Edison Company on April 26, 1990

The findings and conclusions of the SALP Board are documented in Report No. 50-456/90001; 50-457/90001 and were discussed with the licensee on April 26, 1990, at Braidwood Station Training Facility.

While the meeting was primarily a discussion between the licensee and NRC, it was open to members of the public as observers.

The following licensee and NRC personnel were in attendance, as well as the noted observer.

Commonwealth Edison Company

B. L. Thomas, President
L. O. DeGeorge, Assistant Vice President, Quality Prog. and Assess.
T. J. Maiman, Vice President PWR - Operations
D. Elias, PWR Projects Manager
R. E. Querio, Station Manager
S. C. Hunsader, Licensing Administrator
Other licensee personnel

Nuclear Regulatory Commission

C. J. Paperiello, Deputy Regional Administrator, RIII
W. L. Forney, Deputy Director, Division of Reactor Projects, RIII
S. P. Sands, Acting Chief, Section 1A, Division of Reactor Projects, RIII
T. M. Tongue, Senior Resident Inspector, Braidwood
J. A. Hopkins, Resident Inspector, Braidwood

Other

Jeffrey L. Roman, IDNS Resident Engineer

B. Comments Received from Licensee

Commonwealth Edison Company response to the Braidwood Initial SALP 9 Report dated May 15, 1990, had no comments requiring revision to the specific content of the report. Because there is no revision, the Initial SALP Report is considered the Final SALP Report.