



THE GENERAL CRUSHED STONE COMPANY

A Subsidiary of KOPPERS COMPANY, INC.

(717) 326-9031

EASTON, PENNSYLVANIA 18042

3485 West Fourth Street
P.O. Box 3513
Williamsport, Pa. 17701

MS=12

P2

June 25, 1984

Nuclear Regulatory Commission
Region 1
631 Park Avenue
King of Prussia, PA 19406

Re: Docket No. 030-21088
Control No. 17630

Gentlemen:

Please attach the following information to our application for a byproduct material license, dated May 30, 1984, to Item #15: Operators Instructions.

- 10) The operator shall never leave the gauge unattended while on a temporary job site. When not in use, the gauge should be kept in a locked vehicle in its' proper container no less than 30 centimeters from any personnel. At the end of each working day the gauge is to be returned to its permanent storage location.
- 11) The operator shall never perform any maintenance on the gauges that involves dismantling, removal of the source holder, or any service that may result in unnecessary exposure to radiation. Any such maintenance must only be performed by the manufacturer of the gauge.

If any additional information is required, please contact me at our office.

Sincerely,

J. Glenn Shawl

JGS:lo

RECEIVED-REGION 1
JUN 27 PM 2:23
"OFFICIAL COPY"

MLP

17630

8408150047 840720
NMS LIC30
37-23445-01 PDR

JUN 27 1984