




**GULF STATES UTILITIES COMPANY**

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704

AREA CODE 713 838-6631

July 30, 1984  
RBG-18367  
File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator  
U.S. Nuclear Regulatory Commission  
Region IV, Office of Inspection and Enforcement  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76001



Dear Mr. Collins:

River Bend Station Unit 1  
Docket No. 50-458  
Interim Report/DR-188

An interim or final status report concerning the hubs on socket-weld flanges supplied by Guyon Alloys for the instrument lines on the Main Steam Isolation System will be provided by August 29, 1984.

Sincerely,

*L. A. England for*

J. E. Booker  
Manager - Engineering,  
Nuclear Fuels & Licensing  
River Bend Nuclear Group

JEB/PJD/lp

cc: Director of Inspection & Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

NRC Resident Inspector - Site

8408150177 840730  
PDR ADOCK 05000458  
S PDR

*Le-27*  
*1/0*