

UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION IV

611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-8064

NOV - 8 1995

TU Electric

ATTN: C. L. Terry, Group Vice President

Nuclear Production

Energy Plaza

1601 Bryan Street, 12th Floor

Dallas, Texas 75201-3411

SUBJECT: NRC INSPECTION REPORT 50-445/95-21; 50-446/95-21 AND NOTICE OF

VIOLATION

This letter refers to the inspection conducted by Ms. Gail M. Good and Mr. Thomas R. Meadows of this office on September 25-29, 1995, at the Comanche Peak Steam Electric Station, Units 1 and 2, facility. The purpose of the inspection was to determine whether activities authorized by the license were conducted safely and in accordance with NRC requirements. At the conclusion of the inspection, the findings were discussed with Mr. Wesley M. Taylor, yourself, and those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Based on the results of this inspection, the NRC has determined that one violation of NRC requirements occurred. This violation is cited in the enclosed Notice of Violation (Notice) and the circumstances surrounding it are described in detail in the subject inspection report. This violation is of concern because it involves protection of plant personnel and because it was identified by the NRC.

The NRC has concluded that information regarding the reason for the violation, the corrective actions taken and planned to correct the violation and prevent recurrence is already adequately addressed in the enclosed report. Therefore, you are not required to respond to this letter unless the description therein does not accurately reflect your corrective actions or your position. In that case, or if you choose to provide additional information, you should follow the instructions specified in the enclosed Notice.

In addition to the violation, one exercise weakness was identified during the simulator walkthroughs as discussed in Section 4.1.2 of the enclosed inspection report. The weakness involved failure of the Control Room to take appropriate actions to protect plant personnel.

According to 10 CFR Part 50. Appendix E.IV.F.2.g, exercise weaknesses are inspection findings that need to be corrected by the licensee. You are requested to provide this office with a description of your corrective measures and your schedule for completing these actions within 30 days after receipt of this letter.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice." a copy of this letter, its enclosure(s), and your response will be placed in the NRC Public Document Room (PDR). To the extent possible, your response should not include any personal privacy, proprietary, or safeguards information so that it can be placed in the PDR without redaction.

The response directed by this letter and the enclosed Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, Pub. L. No. 96.511.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely.

Thomas P. Gwynn, Director Division of Reactor Safety

Dockets: 50-445

50-446

Licenses: NPF-87

NPF-89

Enclosures:

Notice of Violation
 NRC Inspection Report

50-445/95-21: 50-446/95-21

w/attachments

cc w/enclosures:

TU Electric

ATTN: Roger D. Walker, Manager of Regulatory Affairs for Nuclear

Engineering Organization

Energy Plaza 1601 Bryan Street, 12th Floor Dallas, Texas 75201-3411 Juanita Ellis President - CASE 1426 South Polk Street Dallas, Texas 75224

TU Electric Bethesda Licensing 3 Metro Center, Suite 610 Bethesda, Maryland 20814

Morgan, Lewis & Bockius ATTN: George L. Edgar, Esq. 1800 M. Street, NW Washington, D.C. 20036

Texas Department of Licensing & Regulation ATTN: G. R. Bynog, Program Manager/ Chief Inspector Boiler Division P.O. Box 12157, Capitol Station Austin, Texas 78711

Honorable Dale McPherson County Judge P.O. Box 851 Glen Rose, Texas 76043

Texas Radiation Control Program Director 1100 West 49th Street Austin, Texas 78756

Office of the Governor
ATTN: Susan Rieff, Director
Environmental Policy
P.O. Box 12428
Austin. Texas 78711

Chief. Technological Hazards Branch FEMA Region 6 Federal Regional Center 800 North Loop 288 Denton, Texas 76201-3698 E-Mail report to D. Nelson (DJN) E-Mail report to NRR Event Tracking System (IPAS)

bcc to DMB (IE01)

bcc distrib. by RIV:

L. J. Callan Branch Chief (DRP/B) MIS System RIV File Branch Chief (DRP/TSS) B. Murray, DRS/PSB T. R. Meadows, DRS/OSB

Resident Inspector (2) Leah Tremper (OC/LFDCB, MS: TWFN 9E10) DRS-PSB (Goines) Project Engineer (DRP/B) T. Essig (NRR/PERB, MS: OWFN 9H15)

11/8/95

11/8 /95

DOCUMENT NAME: R:\CP521RP.GMG *Previously concurred
To receive copy of document, indicate in box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy DUCUMENT NAME: RIV: PSB OSB C: PSB DD: DRS D: DRP 1/ D: DRS . 1 GMGood: nh* TRMeadows* BMurray* KEBrockman // JEDyer V TPGwynn Lu

11/6/95 OFFICIAL RECORD COPY

/95

195

11/ /95

E-Mail report to D. Nelson (DJN) E-Mail report to NRR Event Tracking System (IPAS)

bcc to DMB (IEO1)

bcc distrib. by RIV:

L. J. Callan Branch Chief (DRP/B) MIS System RIV File Branch Chief (DRP/TSS) B. Murray, DRS/PSB T. R. Meadows, DRS/OSB Resident Inspector (2) Leah Tremper (OC/LFDCB, MS: TWFN 9E10) DRS-PSB (Goines) Project Engineer (DRP/B) T. Essig (NRR/PERB, MS: OWFN 9H15)

DOCUMENT NAME: R:\CP521RP.GMG *Previously concurred
To receive copy of document, indicate in box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy RIV: PSB OSB C: PSB JOD: DRS N D: DRP(1/ D:DRS GMGood:nh* TRMeadows* BMurray* KEBrockman // JEDyer () TPGwynn La 11/ /95 11/ /95 /95 11/6/95 11/8 /95 11/8/95

OFFICIAL RECORD COPY