

POST OFFICE BOX 2951 · BEAUMONT, TEXAS 77704 AREA CODE 713 838-6631

> July 30, 1984 RBG- 18369 File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator U. S. Nuclear Regulatory Commission Region IV, Office of Inspection and Enforcement 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76001

GE 16 - 6F

12:27 10

Dear Mr. Collins:

River Bend Station Unit 1 Docket No. 50-458 Interim Report/DR-214

An interim or final status report concerning gauges on the seating surface in the stainless steel overlay area of the cover on a feed check valve supplied by Atwood and Morrill will be provided by September 5, 1984.

Sincerely,

L. G. England for

J. E. Booker Manager - Engineering, Nuclear Fuels & Licensing River Bend Nuclear Group

JEB/PJD/1p

8408150707 840 PDR ADOCK 0500

cc: Director of Inspection & Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20505

NRC Resident Inspector - Site