

AUG 8 1984

DMB 016

Docket No. 50-346

DISTRIBUTION

<u>Docket File</u>	Ade Agazio
NRC-PDR	RIngram
L PDR	Gray File
ORB#4 Rdg	
DEisenhut	
OELD	
EJordan	
JNGrace	
EBlackwood	
Hornstein	
ACRS-10	

Mr. Richard P. Crouse
Vice President, Nuclear
Toledo Edison Company
Edison Plaza - Stop 712
300 Madison Avenue
Toledo, Ohio 43652

Dear Mr. Crouse:

SUBJECT: PROCEDURES GENERATION PACKAGE - EMERGENCY OPERATION GUIDELINES

Toledo Edison Company submitted a Procedures Generation Package (PGP) as required by Supplement 1 to NUREG-0737, on March 1, 1984 (Serial No. 1030). The Emergency Operation Guidelines (EOG) are part of the PGP. The NRC staff has reviewed and approved (Reference 1) the EOG submitted for Oconee 3, which is also a B&W reactor. The B&W Owners Group informed us on June 8, 1984 (Reference 2) that individual B&W licensees will prepare documents "which will address the differences between the PGPs and the Oconee guideline directly." Consistent with the B&W Owners Group commitment, we request you to justify the adequacy of the Davis-Besse plant-specific technical guidelines by referencing the Oconee guideline as applicable, and by identifying and justifying safety significance differences between your guidelines and those we have reviewed for Oconee. Please provide your response no later than September 14, 1984.

The information requested in this letter affects fewer than ten respondents; therefore, OMB clearance is not required under P.L. 96-511.

Sincerely,

ORIGINAL SIGNED BY
JOHN F. STOLZ

John F. Stolz, Chief
Operating Reactors Branch #4
Division of Licensing

cc: See next page

Reference 1 Safety Evaluation of "Abnormal Transient Operating Guidelines", Generic Letter 83-31, dated September 14, 1983.

Reference 2 Letter, J. R. Lingenfelter to D. G. Eisenhut, "B&W Owners Group Plan and Schedule for Addressing the Safety Evaluation of ATOG (TMI Item I.C.1)", dated June 8, 1984.

ORB#4:DL
Ade Agazio
8/8/84

ORB#4:DL
JStolz
8/8/84

Toledo Edison Company

cc w/enclosure(s):

Mr. Donald H. Hauser, Esq.
The Cleveland Electric
Illuminating Company
P. O. Box 5000
Cleveland, Ohio 44101

U.S. Nuclear Regulatory Commission
Resident Inspector's Office
5503 N. State Route 2
Oak Harbor, Ohio 43449

Gerald Charnoff, Esq.
Shaw, Pittman, Potts
and Trowbridge
1800 M Street, N.W.
Washington, D. C. 20036

Paul M. Smart, Esq.
Fuller & Henry
300 Madison Avenue
P. O. Box 2088
Toledo, Ohio 43603

Regional Radiation Representative
EPA Region V
230 South Dearborn Street
Chicago, Illinois 60604

Mr. Robert B. Borsum
Babcock & Wilcox
Nuclear Power Generation Division
7910 Woodmont Avenue, Suite 220
Bethesda, Maryland 20814

Ohio Department of Health
ATTN: Radiological Health
Program Director
P. O. Box 118
Columbus, Ohio 43216

President, Board of County
Commissioners of Ottawa County
Port Clinton, Ohio 43452

Attorney General
Department of Attorney General
30 East Broad Street
Columbus, Ohio 43215

James W. Harris, Director (Addressee Only)
Division of Power Generation
Ohio Department of Industrial Relations
2323 West 5th Avenue
P. O. Box 825
Columbus, Ohio 43216

Harold Kohn, Staff Scientist
Power Siting Commission
361 East Broad Street
Columbus, Ohio 43216

Mr. James G. Keppler, Regional Administrator
U. S. Nuclear Regulatory Commission, Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Mr. Robert F. Peters
Manager, Nuclear Licensing
Toledo Edison Company
Edison Plaza
300 Madison Avenue
Toledo, Ohio 43652



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555

August 8, 1984

Docket No. 50-346

Mr. Richard P. Crouse
Vice President, Nuclear
Toledo Edison Company
Edison Plaza - Stop 712
300 Madison Avenue
Toledo, Ohio 43652

Dear Mr. Crouse:

SUBJECT: PROCEDURES GENERATION PACKAGE - EMERGENCY OPERATION GUIDELINES

Toledo Edison Company submitted a Procedures Generation Package (PGP) as required by Supplement 1 to NUREG-0737, on March 1, 1984 (Serial No. 1030). The Emergency Operation Guidelines (EOG) are part of the PGP. The NRC staff has reviewed and approved (Reference 1) the EOG submitted for Ocone 3, which is also a B&W reactor. The B&W Owners Group informed us on June 8, 1984 (Reference 2) that individual B&W licensees will prepare documents "which will address the differences between the PGPs and the Ocone guideline directly." Consistent with the B&W Owners Group commitment, we request you to justify the adequacy of the Davis-Besse plant-specific technical guidelines by referencing the Ocone guideline as applicable, and by identifying and justifying safety significance differences between your guidelines and those we have reviewed for Ocone. Please provide your response no later than September 14, 1984.

The information requested in this letter affects fewer than ten respondents; therefore, OMB clearance is not required under P.L. 96-511.

Sincerely,

George R. Rintank
John F. Stolz, Chief
Operating Reactors Branch #4
Division of Licensing

cc: See next page

Reference 1 Safety Evaluation of "Abnormal Transient Operating Guidelines", Generic Letter 83-31, dated September 14, 1983.

Reference 2 Letter, J. R. Lingenfelter to D. G. Eisenhut, "B&W Owners Group Plan and Schedule for Addressing the Safety Evaluation of ATOG (TMI Item I.C.1)", dated June 8, 1984.