

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

August 13, 1984

TELEPHONE
(704) 373-4531

Mr. Harold R. Denton, Director
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555


Attention: Ms. E. G. Adensam, Chief
Licensing Branch No. 4

Re: McGuire Nuclear Station
Docket Nos. 50-369, 50-370

Dear Mr. Denton:

Please refer to our letter of August 2, 1984, concerning the McGuire Nuclear Station spent fuel pool two region rerack modifications. A typographical error was identified on page 6 of the additional information attachment, therefore a corrected version of the page is attached. Also, please note that only Page 1 of the Attachment on the August 2, 1984 letter is considered proprietary to Westinghouse.

Very truly yours,



Hal B. Tucker

WHM:glb


Attachment

cc: Mr. J. P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Suite 2900
101 Marietta Street, NW
Atlanta, Georgia 30323

Mr. W. T. Orders
Senior Resident Inspector
McGuire Nuclear Station

A001
11

Region 1 11 x 13 Rack (East/West Seismic)



	Linear	Non-Linear	
		1 Cell	11 x 13
Total Load	242840	1679	240100
Dead Weight	120000	847	121100
Ratio (Total/Dead Weight)	2.023	1.98	1.98