11 Pulled

October 27, 1995

Mr. E. Watzl, Vice President Nuclear Generation Northern States Power Company 414 Nicollet Mall Minneapolis, MN 55401

SUBJECT: NRC INSPECTION REPORT NOS. 50-282/95012; 50-306/95012

Dear Mr. Watzl:

This refers to the routine safety inspection conducted by Mr. R. Bywater and others of this office from August 22, 1995, through October 10, 1995. The inspection included a review of activities at the Prairie Island Nuclear Generating Plant authorized by NRC Operating License Nos. DPR-42 and DPR-60. At the conclusion of the inspection, the findings were discussed with Mr. J. Sorensen and other members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel. The purpose of the inspection was to determine whether activities authorized by the licenses were conducted safely and in accordance with NRC requirements.

No violations of NRC requirements were identified during the course of this inspection. Your efforts in preparing for the service water system self-assessment, and conducting the self-assessment were excellent.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room.

We will gladly discuss any questions you may have concerning this inspection.

michael J. Jordan, Chief Reactor Projects Branch 7

Sincerely,

9511280023 951027 PDR ADOCK 05000282 Q PDR

> Docket No. 50-282 Docket No. 50-306

Enclosure: Inspection Report

No. 50-282/95012; 50-306/95012

See Attached Distribution

2801

Distribution:

cc w/encl: Plant Manager, Prairie Island

John W. Ferman, Ph.D., Nuclear Engineer, MPCA State Liaison Officer, State

of Minnesota

State Liaison Officer, State

of Wisconsin Tribal Council

Prairie Island Dakota Community

Distribution: Docket File w/encl PUBLIC IE-01 w/encl OC/LFDCB w/encl SRI Prairie Island. Monticello w/encl

DRP w/encl RIII PRR w/encl Prairie Island PM, NRR w/encl IPAS (E-Mail) w/encl

Document: R:\insprpts\powers\prai\pra95012.dpr
To receive a copy of this document, indicate in the box "C" = Copy without attach/encl "E" = Copy with attach/encl "N" =

OFFICE	RIII	RIII	N	RILI	E	RIII	N
NAME	Nelson/Jordan/	Ring		creed P		Jacobson A	
DATE	10/25/95	10/26/95		10/04/95		10/26/95	

OFFICIAL RECORD COPY

STATE OF THE STATE

UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION III 801 WARRENVILLE ROAD LISLE, ILLINOIS 60532-4351 October 27, 1995

Mr. E. Watzl, Vice President Nuclear Generation Northern States Power Company 414 Nicollet Mall Minneapolis, MN 55401

SUBJECT: NRC INSPECTION REPORT NOS. 50-282/95012; 50-306/95012

Dear Mr. Watzl:

This refers to the routine safety inspection conducted by Mr. R. Bywater and others of this office from August 22, 1995, through October 10, 1995. The inspection included a review of activities at the Prairie Island Nuclear Generating Plant authorized by NRC Operating License Nos. DPR-42 and DPR-60. At the conclusion of the inspection, the findings were discussed with Mr. J. Sorensen and other members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel. The purpose of the inspection was to determine whether activities authorized by the licenses were conducted safely and in accordance with NRC requirements.

No violations of NRC requirements were identified during the course of this inspection. Your efforts in preparing for the service water system self-assessment, and conducting the self-assessment were excellent.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room.

We will gladly discuss any questions you may have concerning this inspection.

Sincerely,

Michael J. Jordan, Chief Reactor Projects Branch 7

Docket No. 50-282 Docket No. 50-306

Enclosure: Inspection Report

No. 50-282/95012; 50-306/95012

See Attached Distribution

E. Watz1 -2-

Distribution:

cc w/encl: Plant Manager, Prairie Island

John W. Ferman, Ph.D., Nuclear Engineer, MPCA State Liaison Officer, State

of Minnesota

State Liaison Officer, State

of Wisconsin Tribal Council

Prairie Island Dakota Community