DUKE POWER COMPANY P.O. BOX 33189 CHARLOTTE, N.G. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

18 Hy JEH, 3/1984 9: 09

TELEPHONE (704) 373-4531

Mr. James P. O'Reilly, Regional Administrator U. S. Nuclear Regulatory Commission Region II 101 Marietta Street, NW, Suite 2900 Atlanta, Georgia 30323

Re: Catawba Nuclear Station Unit 1 Docket Nos. 50-413 SD 413/84-01

Dear Mr. O'Reilly:

In my letter of April 20, 1984 transmitting an interim report on the subject deficiency, it was stated that additional vibration testing would be done after fuel loading and a supplementary report of the results would be issued by August 13, 1984. This date was contingent on the May schedule for fuel loading and heat-up.

Since fuel loading was delayed until the 19th of July, we have rescheduled the completion of this testing and will forward the supplementary report of our evaluation by November 1, 1984.

Very truly yours,

#.B. Tuch 1stell

Hal B. Tucker

LTP/rhs

Attachment

cc: Director Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

> NRC Resident Inspector Catawba Nuclear Station

Palmetto Alliance 2135½ Devine Street Columbia, South Carolina 29205

INPO Records Center Suite 1500 1100 Circle 75 Parkway Atlanta, Georgia 30339 Mr. Robert Guild, Esq. Attorney-at-Law P. O. Box 12097 Charleston, South Carolina 29412

Mr. Jesse L. Riley Carolina Environmental Study Group 854 Henley Place Charlotte, North Carolina 28207

OFFICIAL COPY

8408160468 840726 PDR ADOCK 05000413 S PDR

IE27 1