

SAFETY INSPECTION

1. LICENSEE <i>Downard & Associates, Inc.</i> <i>4750 North 40th Street</i> <i>Sioux Falls, SD 57105</i>		2. REGIONAL OFFICE REGION III U.S. NUCLEAR REGULATORY COMMISSION 799 ROOSEVELT ROAD GLEN ELLYN IL 60137	
3. DOCKET NUMBER(S) <i>030-22312</i>	4. LICENSE NUMBER(S) <i>48-18608-02</i>	5. DATE OF INSPECTION <i>27 MARCH 1992</i>	

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The findings as a result of this inspection are as follows:

- 1. Within the scope of this inspection, no violations were observed.
- 2. The inspector also verified the steps you have taken to correct the violations identified during the last inspection. We have no further questions on those actions at this time.
- 3. During this inspection certain of your activities, as described below or attached, were in violation of NRC requirements. This form is a **NOTICE OF VIOLATION**, which is required to be posted in accordance with 10 CFR 19.11.
 - A. _____ was not properly posted to indicate the presence of a _____, 10 CFR 30.203(b), (c), (d), (e) or 34.42.
 - B. _____ of sealed sources were not performed at the proper frequencies. 10 CFR _____ or License Condition Number _____.
 - C. Records of _____ were not properly maintained. 10 CFR _____ or License Condition Number _____.
 - D. Documents were not properly posted or otherwise made available. 10 CFR 19.11.
 - E. Reports or notification of _____ were not made in accordance with 10 CFR _____ or License Condition Number _____.
 - F. _____

IEOT

110

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified in the items checked above. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201. No further response will be submitted unless required by the NRC.

SIGNATURE - LICENSEE <i>9204100087 920327</i> <i>REG3 LIC30</i> <i>48-18608-02 PDR</i>	DATE	SIGNATURE - NRC INSPECTOR <i>[Signature]</i>	DATE <i>[Signature]</i>
---	------	---	----------------------------

FORD 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9204100091 DOC. DATE: 92/03/31 NOTARIZED: NO
FACIL:
AUTH. NAME AUTHOR AFFILIATION
SIMMONS, F.L. Region 3 (Post 820201)
RECIP. NAME RECIPIENT AFFILIATION
STEIN, F. Ladish Co.

DOCKET #
03017956

SUBJECT: Forwards safety insp on 920317 of license 48-20096-01. No
No violations noted.

DISTRIBUTION CODE: IE07D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+1
TITLE: Environ & Radiological (30,40,70 DKT)-Insp Rept/Notice of Viol Respon

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	LA	1 1	PM	1 1
INTERNAL:	AEOD/DSP/NAS	1 1	NMSS/IMAB 6H3	1 1
	NMSS/IMOB 6H3	1 1	NMSS/SGDB 4E4	1 1
	NMSS/SGTB 4E4	1 1	NUDOCS-ABSTRACT	1 1
	OE DIR	1 1	RGN. <u>HL</u> .FILE 01	1 1
EXTERNAL:	LPDR	0 0	NRC PDR	1 1

R
I
D
S
/
F
O
R
D
1
D
O
C
U
M
E
N
T

TOTAL NUMBER OF COPIES REQUIRED: LTTR 11 ENCL 11