

- 3.5 IF the selected FW level transmitter has failed,
THEN transfer to the alternate level transmitter.
- 3.6 IF recirc. runback occurred,
THEN reset runback per S43.0.B.
- 3.7 IF third Condensate Pump is not available,
THEN maintain RFP suction pressure above 300 p.s.i.g by
limiting Reactor power.

4.0 VERIFICATION OF AUTOMATIC ACTIONS

<u>Actions</u>	<u>Conditions</u>
4.1 Recirc. reduced to speed corresponding to 62% rated core flow	One RFP with less than 20% flow <u>AND</u> low Reactor level (27.5") <u>OR</u> One Condensate Pump tripped with total Feedwater flow greater than 85%
4.2 Recirc. runback to 28% of indicated speed	Total Feedwater flow less than 20% <u>OR</u> low Reactor level (12.5") <u>OR</u> Pump discharge valve less than 90% open
4.3 REACTOR HI-LO LEVEL alarm	30"
4.4 Scram Group II Isolation	12.5"

DATE 04/03/92 09:52

NRMS RECEIPT ACKNOWLEDGEMENT

SEQUENCE # 3924020840

LGS PROCEDURES - APPROVED ORIGINALS
DISTRCDDE OT-U1

TO: NRC OFFSITE

PROCDNO OT-100
REVISION 009
DATE 04/01/92

☞ I HAVE RECEIVED THE SUBJECT MATERIAL

SIGNATURE: _____ DATE: _____

PLEASE RETURN THIS FORM PROMPTLY TO LGS ADMIN. SERVICES (LGS-340)
WITHIN 15 DAYS OF THE ABOVE PRINT-DATE.

140000

Add: DRR (DREP) (PEP)
A001
0/1

LGS PROCEDURES - APPROVED ORIGINALS
DISTR CODE DT-U1

```
*****
*LGS SIMULATOR          LGS-LTC          01 C**LGS OFFICE          DCC/WALK          01 I*
*LGS TRAIN CTR          LGS-LTC          03 C**NUNEZ, R.          LGS-LTC          01 I*
*MAINT/IGC LIBRARY      DCC/WALK          01 I**OPERATIONS SUP. CTR. DCC/WALK          01 I*
*NRC OFFSITE            OUTGOING          01 C**PLANT OP. SUP. FAC. DCC/WALK          01 I*
*TRAINING COORDIN.      DCC/WALK          01 I**SHIFT MGR OFFICE    DCC/WALK          01 I*
*CONST BLDG LIB         DCC/WALK          01 I**SUPPT BLDG LIB #1    DCC/WALK          01 I*
*CONTROL RM CART LGS    DCC/WALK          02 I**SUPPT BLDG LIB #2    DCC/WALK          01 I*
*EMERG. OP. FAC. LGS    DCC/WALK          01 C**TECH. SUPP. CTR. LGS DCC/WALK          01 I*
*INPO                    OUTGOING          01 I**
*LGS LIBRARY            LGS/A2-1          01 I**
*****
```

REQUESTS FOR CHANGES TO THIS DISTRIBUTION LIST MUST BE ADDRESSED TO THE ORGANIZATION RESPONSIBLE FOR ORIGINATING THE ATTACHED DOCUMENT (SEE NUCLEAR RELATED DOCUMENT REGISTER (NRDR) FOR RESP. ORG.). THE RESP. ORG. WILL AUTHORIZE THE LOCAL DAC SUPERVISOR TO MAKE THE NECESSARY CHANGES.

ATTACHED IS A COPY OF:
PROCEDNO DT-100
REVISION 009
DATE 04/01/92

UNCONTROLLED: LIBRARY, INPO, NUNEZ, R.

INPO - DT-100, 100 BASES, 101, 101 BASES, 103, 103 BASES, 104 ,
104 BASES, 112, 112 BASES, 116, 116 BASES