

WOLF CREEK

NUCLEAR OPERATING CORPORATION

Bart D. Withers
President and
Chief Executive Officer

April 14, 1992
WM 92-0065

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Mail Station P1-137
Washington, D. C. 20555


Subject: Docket No. 50-482; Inservice Inspection Summary Report
for the Fifth Refueling Outage

Gentlemen:

The purpose of this letter is to provide the Inservice Inspection Summary Report for the fifth refueling outage at Wolf Creek Generating Station (WCGS). This report is being submitted in accordance with ASME Boiler and Pressure Vessel Code 1980 Edition through Winter 1981 Addenda, Section XI Article IWA 6000 Paragraph 6230. Records and reports documenting the inspections are maintained at WCGS and are available for review upon request.

If you have any questions concerning this matter, please contact me or Mr. S. G. Wideman of my staff.

Very truly yours,



Bart D. Withers
President and
Chief Executive Officer

BDW/jra

Attachment

cc: A. T. Howell (NRC), w/a
R. D. Martin (NRC), w/a
G. A. Pick (NRC), w/a
W. D. Reckley (NRC), w/a

9204170149 920414
PDR ADOCK 05000482
G PDR

Adair
11