

AUG 14 1984

Docket No.: 50-412

Mr. Earl J. Woolever, Vice President
Nuclear Construction Division
Duquesne Light Company
Robinson Plaza Building No. 2
Suite 210
PA Route 60
Pittsburgh, PA 15205

Dear Mr. Woolever:

Subject: Beaver Valley Unit 2 Safety Review Request for Additional Information

In the process of reviewing your May 18, 1983 application for an operating license for Beaver Valley Power Station, Unit 2 (BVPS-2), the staff has determined the need for additional information. The specific information required is identified in the enclosed request for information.

We request that you review the enclosure and provide a response within one month of receipt of this letter. Should you have any questions concerning this request, please contact Licensing Project Managers Marilyn Ley (301) 492-7792 or Manny Licitra (301) 492-7200.

George W. Knighton, Chief
Licensing Branch No. 3
Division of Licensing

Enclosure: As stated

cc: See next page

DISTRIBUTION

~~Docket File~~

- NRC PDR
- Local PDR
- PRC System
- NSIC
- LB#3 Reading
- JLee
- MLey
- MLicitra
- OParr
- JWermiel
- RAnand
- OELD, Attorney
- ACRS (16)
- EJordan
- NGrace

DL: <i>MLey</i>	DL:LB#3 <i>MLey</i>	DL: <i>GK</i>
<i>M. Ley</i>	MLicitra	GK Knighton
8/10/84	8/10/84	8/13/84

8408230377 840814
PDR ADOCK 05000412
A PDR

REQUEST FOR ADDITIONAL INFORMATION

- 410.54 In regard to internally generated missile protection inside and outside of containment (i.e., SRP Section 3.5.1.1 and 3.5.1.2), we are unable to confirm that you have properly assumed a single active failure concurrent with postulated internally generated missiles. Verify that redundant safety-related trains are protected from damage which may result from the impact of missiles generated from nonsafety-related sources consistent with the guidelines of Position C.2 of Regulatory Guide 1.29.
- 410.55 Verify that the instrumentation provided for indication of loss of component cooling water to the reactor coolant pumps is safety grade (in accordance with IEEE 279) as identified in Part 4d. of the Review Procedures of SRP Section 9.2.2.

Beaver Valley

Mr. Earl J. Woolever
Vice President, Nuclear Construction
Duquesne Light Company
Robinson Plaza Building, No. 2, Suite 210
PA Route 60
Pittsburgh, Pennsylvania 15205

Gerald Charnoff, Esq.
Jay E. Silberg, Esq.
Shaw, Pittman, Potts & Trowbridge
1800 M Street, N.W.
Washington, DC 20036

Mr. C. W. Ewing, Quality Assurance
Manager
Quality Assurance Department
Duquesne Light Company
P. O. Box 186
Shippingport, Pennsylvania 15077

Mr. R. J. Washabaugh
BV-2 Project Manager
Duquesne Light Company
Robinson Plaza Building No. 2
Suite 210
Pittsburgh, Pennsylvania 15205

Mr. T. J. Lex
Westinghouse Electric Corporation
Power Systems
P. O. Box 355
Pittsburgh, Pennsylvania 15230

Mr. P. RaySircar
Stone & Webster Engineering Corporation
P. O. Box 2325
Boston, Massachusetts 02107

Mr. Glenn Walton
U. S. NRC
P. O. 181
Shippingport, Pennsylvania 15077

Mr. Thomas E. Murley, Regional Admin.
U. S. NRC, Region I
631 Park Avenue
King of Prussia, Pennsylvania 15229

Mr. H. M. Siegel, Manager Engineering
Beaver Valley Two Project
Duquesne Light Company
Robinson Plaza Building No. 2
Suite 210
PA Route 60
Pittsburgh, Pennsylvania 15205

Zori Ferkin
Assistant Counsel
Governor Energy Council
1625 N. Front Street
Harrisburg, PA 15105

Director, Pennsylvania Emergency
Management Agency
Room B-151
Transportation & Safety Building
Harrisburg, Pennsylvania 17120

Mr. Thomas Gerusky
Bureau of Radiation Protection
PA Department of Environmental
Resources
P. O. Box 2063
Harrisburg, Pennsylvania 17120

BVPS-2 Records Management Supervisor
Duquesne Light Company
Post Office Box 4
Shippingport, Pennsylvania 15077

John A. Lee, Esq.
Duquesne Light Company
1 Oxford Centre
301 Grant Street
Pittsburgh, Pennsylvania 15279

Mr. E. F. Kurtz, Jr., Manager
Regulatory Affairs
Beaver Valley Two Project
Duquense Light Company
Robinson Plaza Buidling No. 2
Suite #210
PA Route 60
Pittsburgh, Pennsylvania 15205