AUG 2 1 1984

Carolina Power and Light Company
ATTN: Mr. E. E. Utley
Executive Vice President
Power Supply and Engineering
and Construction
411 Fayetteville Street
Raleigh, NC 27602

Gentlemen:

SUBJECT: REPORT NOS. 50-261/84-24, 50-324/84-16, 50-325/84-16, AND 50-400/84-18

The NRC Systematic Assessment of Licensee Performance (SALP) Board has completed its periodic evaluation of the performance of the subject facilities. The Robinson, Brunswick, and Harris facilities were evaluated for the period February 1, 1983, through April 30, 1984. The results of the evaluation are documented in the enclosed SALP Board Assessment. In the past, as a part of the SALP program, we have routinely met with Carolina Power and Light Company officials to discuss the results of the SALP Board's evaluation. The format of the SALP program has recently been revised so that this meeting is no longer a requirement, but may be held as a public meeting at the discretion of the licensee or NRC. In consideration of this revised format, please contact this office within ten days of the date of this letter to discuss the need for a meeting.

The performance of your Robinson and Brunswick facilities was evaluated in the operational functional areas of plant operations, radiological controls, maintenance, surveillance, fire protection, emergency preparedness, security and safeguards, refueling, licensing activities, and the quality assurance program. Harris was evaluated in the construction functional areas of soils and foundations, containment and other safety related structures, piping systems and supports, safety related components, support systems, electrical power supply and distribution, licensing activities, and the quality assurance program.

The SALP Board evaluation process consists of categorizing performance and the performance trend in each functional area. The categories which we have used to evaluate the performance and the performance trend of your facilities are defined in section II of the enclosed SALP Board Assessment. Any comments which you have concerning our evaluation of the performance of your facilities should be submitted to this office within 20 days following the date of this letter or the date of the meeting on this SALP assessment (if held).

Your comments, if any, and the SALP Board Assessment, will both appear as enclosures to the Region II Administrator's letter which issues the SALP Board Assessment as an NRC Report. In addition to the issuance of the assessment, this letter will, if appropriate, state the NRC position on matters relating to the status of your safety programs.

8408240316 840821 PDR ADDCK 05000261 G PDR

IE401

Carolina Power and Light Company

In accordance with 10 CFR 2.790, a copy of this letter and enclosure will be placed in the NRC's Public Document Room unless you notify this office, by telephone, within 10 days of the date of this letter and submit written application to withhold information contained therein within 30 days of the date of this letter. Such application must be consistent with the requirements of 2.790(b)(1).

Should you have any questions concerning this letter, we will be glad to discuss them with you.

Sincerely,

Richard C. Lewis, Director Division of Reactor Projects

Enclosure: SALP Board Assessment for Carolina Power and Light Company

cc w/encl:

P. W. Howe, Vice President Brunswick Nuclear Project

C. R. Dietz, Plant General Manager

G. P. Beatty, Jr., Manager

Robinson Nuclear Project Department

R. E. Morgan, Plant General Manager R. A. Watson, Vice President

Harris Nuclear Project

R. M. Parsons, Project General Manager

bcc w/encl:

NRC Resident Inspectors, Robinson Brunswick, and Harris

D. Price, RII

P. Bemis, RII

A. Hardin, RII

B. Requa, NRR

M. Grotenhuis, NRR

B. Buckley, NRR

L. Grace, IE

R. Starostecki, RI

C. Norelius, RIII

R. Denise, RIV

Records Center, INPO

Region II Distribution Lists C and D

Document Control Desk

State of South Carolina

State of North Carolina

RII	
RVIA	
Hardin	
8/10/84	