AUG23 1984

Docket No. 50-315 Docket No. 50-316

American Electric Power Service Corporation Indiana and Michigan Electric Company ATTN: Mr. John E. Dolan Vice Chairman Engineering and Construction 1 Riverside Plaza Columbus, OH 43216

Gentlemen:

This refers to the NRC's Systematic Assessment of Licensee Performance (SALP) Board Report for the D. C. Cook Nuclear Plant and our meeting of June 21, 1984, which discussed in detail the contents of the report.

Based on the formal exchange of information between our respective staffs, and in the absence of verbal identification of discrepancies within the report or formal written comments from you requiring resolution, no changes to the SALP Board Report are necessary.

Enclosed, as an Appendix to the SALP Board Report, is a summarization of our meeting which includes names of those persons in attendance. Issuance of the Appendix serves as the final step in our SALP assessment process.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter with the referenced enclosure will be placed in the NRC's Public Document Room.

8408280147 840323 PDR ADOCK 05000315 G PDR

American Electric Power Service Corporation

AUG23 1984

No reply to this letter is required; however, should you have questions regarding the SALP Board Report, or Appendix thereto, please let us know and we will be pleased to discuss them with you.

2

Sincerely,

Original signed by James G. Keppler James G. Keppler Regional Administrator

Enclosure: Appendix to SALP Board Report No. 50-315/84-08; 50-316/84-09

cc w/encl:

W. G. Smith, Jr., Plant Manager DMB/Document Control Desk (RIDS) Resident Inspector, RIII Ronald Callen, Michigan Public Service Commission EIS Coordinator, USEPA Region 5 Office R. C. DeYoung, IE H. R. Denton, NRR INPO Regional Administrators RI, RII, RIV, RV

