Arizona Public Service Company 1984 AUS 17 PH 12: 58

REGION VINE

August 13, 1284 ANPP-30190-TDS/TRB

U. S. Nuclear Regulatory Commission Region V Creekside Oaks Office Park 1450 Maria Lane - Suite 210 Walnut Creek, CA 94596-5368

Attention: Mr. T. W. Bishop, Director

Division of Resident

Reactor Projects and Engineering Programs

Time Extension For Report - DER 84-26

A 50.55(e) Potentially Reportable Deficiency Relating To

Improperly Tested Or Adjusted Plunger Interlock.

File: 84-019-026; D.4.33.2

Reference: (A) Telephone conversation between P. Narbut and T. Bradish on

May 10, 1984

(B) ANPP-29646, dated June 4, 1984 (Interim Report)

Dear Sir:

The NRC was notified of a potentially reportable deficiency in Reference (A), and an Interim Report was transmitted by Reference (B). At that time, it was estimated that a Final Report would be available by August 15, 1984.

A Final Report has been submitted to APS for review. It is expected that this Final Report will be transmitted to the NRC by September 15, 1984.

Very truly yours,

EEVan Brunt for E. E. Van Brunt, Jr. APS Vice President Nuclear Production

ANPP Project Director

EEVB/TRB:nj

cc: See Page Two

Mr. T. W. Bishop DER 84-26 Page Two

cc:

Richard DeYoung, Director Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

T. G. Woods, Jr.

D. B. Karner

W. E. Ide

D. B. Fasnacht

A. C. Rogers

L. A. Souza

D. E. Fowler

T. D. Shriver

C. N. Russo

J. Vorees

J. R. Bynum

J. M. Allen

J. A. Brand

A. C. Gehr

W. J. Stubblefield

W. G. Bingham

R. L. Patterson

R. W. Welcher

H. D. Foster

D. R. Hawkinson

L. E. Vorderbrueggen

R. P. Zimmerman

S. R. Frost

J. Self

M. Woods

T. J. Bloom

Records Center Institute of Nuclear Power Operations 1100 Circle 75 Parkway, Suite 1500 Atlanta, GA 30339