

April 29, 1992

Docket No. 50-336

*Docket
File*

MEMORANDUM FOR: John F. Stolz, Director
Project Directorate I-4
Division of Reactor Projects - I/II

FROM: Guy S. Vissing, Senior Project Manager
Project Directorate I-4
Division of Reactor Projects - I/II

SUBJECT: NOTICE OF MEETING WITH NORTHEAST UTILITIES

DATE & TIME: May 19, 1992
9:00 AM - 12:00 noon

LOCATION: U.S. Nuclear Regulatory Commission
One White Flint North, Room 1F19
11555 Rockville Pike
Rockville, Maryland 20852

PURPOSE: To review the onsite and offsite power distribution system design and regulations governing (See enclosed agenda)

PARTICIPANTS*: NRC Guy Vissing
Faust Rosa
James Knight
N. K. Trehan

NU Rick Kacich
David Vail

/s/

Guy S. Vissing, Sr. Project Manager
Project Directorate I-4
Division of Reactor Projects - I/II
Office of Nuclear Reactor Regulation

Enclosure:
Agenda

cc w/enclosure:
See next page

NRC FILE CENTER COPY

*Meetings between NRC technical staff and applicants or licensees are open for interested members of the public, petitioners, intervenors, or other parties to attend as observers pursuant to "Open Meeting Statement of NRC Staff Policy," 43 Federal Register 28058, 6/28/78.

OFFICIAL RECORD COPY

LA:PDI-4
SNorris

PM:PDI-4
GSVissing:cn

DN:PDI-4
JStolz

Document Name: MTGMIL2

4/29/92

4/28/92

4/29/92

9205040259 920429
PDR ADOCK 05003336
P PDR

DFD

DISTRIBUTION - Routine Meeting Notice

Docket File (50-336)

NRC & Local PDRs

PD I-4 Memo

T. Murley/F. Miraglia

J. Partlow

S. Varga

J. Calvo

J. Stolz

G. Vissing

S. Norris

A. Chaffee, EAB

OGC

E. Jordan

B. Grimes

Receptionist - OWFN

F. Rosa

J. Knight

N. K. Trehan

ACRS (10)

GPA/PA

E. Tana, PMAS

P. O'Dell, PMAS

L. Plisco

R. Lobel, EDO

K. Abraham, Region I

C. W. Hehl, RI

Mr. John F. Opeka
Northeast Nuclear Energy Company

Millstone Nuclear Power Station
Unit 2

cc:

Gerald Garfield, Esquire
Day, Berry and Howard
Counselors at Law
City Place
Hartford, Connecticut 06103-3499

R. M. Kacich, Director
Nuclear Licensing
Northeast Utilities Service Company
Post Office Box 270
Hartford, Connecticut 06141-0270

W. D. Romberg, Vice President
Nuclear, Operations Services
Northeast Utilities Service Company
Post Office Box 270
Hartford, Connecticut 06141-0270

D. O. Nordquist
Director of Quality Services
Northeast Utilities Service Company
Post Office Box 270
Hartford, Connecticut 06141-0270

Kevin McCarthy, Director
Radiation Control Unit
Department of Environmental Protection
State Office Building
Hartford, Connecticut 06106

Regional Administrator
Region I
U.S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, Pennsylvania 19406

Bradford S. Chase, Under Secretary
Energy Division
Office of Policy and Management
80 Washington Street
Hartford, Connecticut 06106

First Selectmen
Town of Waterford
Hall of Records
200 Boston Post Road
Waterford, Connecticut 06385

S. E. Scace, Nuclear Station Director
Millstone Nuclear Power Station
Northeast Nuclear Energy Company
Post Office Box 128
Waterford, Connecticut 06385

W. J. Raymond, Resident Inspector
Millstone Nuclear Power Station
c/o U.S. Nuclear Regulatory Commission
Post Office Box 376
Waterford, Connecticut 06385-0376

J. S. Keenan, Nuclear Unit Director
Millstone Unit No. 2
Northeast Nuclear Energy Company
Post Office Box 128
Waterford, Connecticut 06385

Charles Brinkman, Manager
Washington Nuclear Operations
ABB Combustion Engineering
Nuclear Power
12300 Twinbrook Pkwy, Suite 330
Rockville, Maryland 20852

Nicholas S. Reynolds
Winston & Strawn
1400 L Street, NW
Washington, DC 20005-3502

MILLSTONE UNIT NO. 2

GDC-17

NRC/NU MEETING AGENDA

1. Introduction and Background
2. Meeting Purpose
3. Review of Millstone 2 Off-Site and On-Site Power Distribution System Design
 - a. Operation of Overcurrent and Undervoltage Relays
4. Interpretation of Regulatory Criteria
 - a. GDCs 17, 34, 35
 - b. Distinguishing Good Engineering Practices from Design Requirements
 - c. SRPs, Regulatory Guides, IEEE Standards, SECY 77-439
 - d. Application of the Single Failure Criterion
5. Summary and Conclusions