MAR 1 5 19%

The Cleveland Flectric Illuminating Company
ATTN: Mr. R. W. Coan, Vice President,
Technical and Administrative
Services
P.O. Box 5000
Cleveland, Ohio 44101

Docket No. 50-440 7601 Docket No. 50-441

Gentlemen:

. 4.

This refers to the inspection conducted by Messrs. K. R. Naidu and W. J. Key of this office on February 11, 12, and 13, 1976, of activities at Perry Nuclear facilities and to the discussion of our findings with Messrs. Bruckman, Groscup, Marjenin, Sener and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in noncompliance with NRC requirements, as described under Enforcement Items in the Summary of Findings section of the enclosed inspection report.

This notice is sent to you pursuant to the provisions of Section 2.201 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Section 2.201 requires you of this notice a written statement or explanation in reply, action taken and the results achieved; (1) corrective to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this notice, the enclosed inspection report, and your response to this notice will be placed in the NRC's Public

The Cleveland Electric Illuminating Company - 2 -

MAR 1 5 1010

Document Room, except as follows. If this report contains information that you or your contractors believe to be proprietary, you must apply in writing to this office, within twenty days of your receipt of this notice, to withhold such information from public disclosure. The application must include a full statement of the reasons for which the information is considered proprietary, and should be prepared so that proprietary information identified in the application is contained in an enclosure to the application.

We will gladly discuss any questions you have concerning this inspection.

Sincerely yours,

D. M. Humnicutt, Chief Reactor Construction and Engineering Support Branch

Enclosure: IE Inspection Reports No. 050-440/76-01 and No. 050-441/76-01

bcc w/encl:
PDR
Local PDR
NSIC
TIC
HQ Reproduction

DATED TO SEE SECTIONS