Docket Nos. 50-313/92-07 50-368/92-07 License No. DPR-51 NPF-6

Entergy Operations, Inc. ATTN: Mr. Neil S. Carns, Vice President Operations, Arkansas Nuclear One Route 3, Box 137G Russellville, Arkansas 72801

Gentlemen:

SUBJECT: NRC INSPECTION REPORT 50-313/92-07; 50-368/92-07 (NOTICE OF VIOLATION)

This refers to the inspection conducted by Mses. L. J. Smith and K. D. Weaver, and Messrs. I. Barnes, S. J. Campbell, M. A. Satorius, and M. X. Franovich of this office March 1-28, 1992. The inspection included a review of activities authorized for your Arkansas Nuclear One, Units 1 and 2, facility. At the conclusion of the inspection, the findings were discussed with you and those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. The areas included onsite followup of licensee event reports, items of regional interest, onsite response to events, monthly maintenance observation, bimonthly surveillance observation, operational safety verification, and refueling activities.

Based on the results of this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice of Violation. We are concerned that test personnel deviated from the test procedure and pressurized the service water system for hydrostatic testing with an unauthorized revised test boundary established.

Although 10 CFR 2.201 requires you to submit to this office, within 20 days of your receipt to this Notice, a written statement of explanation, we note that the corrective actions being taken adequately address the concerts identified within the Notice of Violation and these actions were reviewed during this inspection. Therefore, no response with respect to this matter is required.

It was also found that the failure of both your primary and secondary analysts to identify seven tubes with indications near the tube sheet on the hot leg side of Steam Generator A during Refueling Outage 2R8 was a violation of 10 CFR Part 50, Appendix B, Criterion V. The violation is not being cited because your efforts to identify and correct the violation met the criteria in Appendix C, paragraph VII, B.(2), of the NRC's "Rules of Practice," 10 CFR Part 2.

R1V: CoopEDRP/A KDWeaver/kw 4/29/92	Intern:DRS MXFranovich 4/29/92,	R1:DRP/A SJCampbell 4/20/92	SRIIDRP/A LJSmith 4/29/92	PE:DRP/A MASatorius 4/29/92	
C:DRP/A WDJohnson 4 /29/92	C:DRS / MOPS IBarnes A /29/92	D DRP Abbeach 5/2 /92			
9205070204	920504				2

PDR ADOCK 05000313

Entergy Operations, Inc.

.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely, Original Signed By: A. B. BEACH

A. Bill Beach, Director Division of Reactor Projects

Enclosures: 1. Appendix A - Notice of Violation 2. Appendix B - NRC Inspection Report 50-313/92-07 50-368/92-07 w/attachment

cc w/enclosures: Entergy Operations, Inc. ATTN: Donald C. Hintz, Executive Vice President & Chief Operating Officer P.O. Box 31995 Jackson, Mississippi 39286

Entergy Operations, Inc. ATTN: John R. McGaha, Vice President Operations Support P.O. Box 31995 Jackson, Mississippi 39286

Wise, Carter, Child & Caraway ATTN: Robert B. McGehee, Esq. P.O. Box 651 Jackson, Mississippi 39205

Arkansas Nuclear One ATTN: Early Ewing, General Manager Technical Support and Assessment Route 3, Box 137G Russellville, Arkansas 72801

Entergy Operations, Inc. ATTN: Jerry Yelverton, General Manager Plant Operations Route 3, Box 137G Russellville, Arkansas 72801

Entergy Operations, Inc.

Slar Ma

Entergy Operations, Inc. ATTN: James J. Fisicaro Director, Licensing Route 3, Box 1376 Russellville, Arkansas 72801

Honorable Joe W. Phillips County Judge of Pope County Pope County Courthouse Russellville, Arkansas 72801

Winston & Strawn ATTN: Nicholas S. Reynolds, Esq. 1400 L Street, N.W. Washington, D.C. 20005-3502

Arkansas Department of Health ATTN: Ms. Greta Dicus, Director Division of Radiation Control and Emergency Management 4815 West Markham Street Little Rock, Arkansas 72201-3867

B&W Nuclear Technologies ATTN: Robert B. Borsum Licensing Representative 1700 Rockville Pike, Suite 525 Rockville, Maryland 20852

Admiral Kinnaird R. McKee, USN (Ret) 214 South Morris Street Oxford, Maryland 21654

ABB Combustion Engineering Nuclear Power ATTN: Charles B. Brinkman Manager, Washington Nuclear Operations 12300 Twinbrook Parkway, Suite 330 Rockville, Maryland 20852

bcc to DMB (IE01)

bcc distrib. by RIV: R. D. Martin DRSS-RPEPS Lisa Shea, RM/ALF DRP PSTS Operator 5.5

Resident Inspector Section Chief (DRP/A) RIV File MIS System Project Engineer (DRP/A)