

Appendix

NOTICE OF VIOLATION

The Detroit Edison Company

Docket No. 50-341

As a result of the inspection conducted June 5-15, 20-22, and July 9-20, 1984, and in accordance with the General Policy and Procedures for NRC Enforcement Actions, (10 CFR, Part 2, Appendix C), the following violation was identified:

10 CFR 50, Appendix B, Criterion V, as implemented by Detroit Edison Nuclear Quality Assurance Program, requires that activities affecting quality be performed in accordance with documented instructions and procedures of a type appropriate to the circumstances.


Contrary to the above, the licensee failed to maintain a correct and up-to-date Temporary Modification Log in the Tagging Center as required by Paragraph 5.3 of POM 12.000.25T.

This is a Severity Level IV violation (Supplement II).

Pursuant to the provisions of 10 CFR 2.201 you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be achieved. Consideration may be given to extending your response time for good cause shown.

AUG 17 1984

Dated _____


R. L. Spessard, Director
Division of Reactor Safety

8409040066 840817
PDR ADOCK 05000341
G PDR