

Omaha Public Power District
444 South 16th Street Mall
Omaha, Nebraska 68102-2247
402/636-2000

January 4, 1996
LIC-96-0001

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Mail Station P1-137
Washington, DC 20555

Reference: Docket No. 50-285

SUBJECT: Transmittal of Changes to the Fort Calhoun Station (FCS) Emergency Plan Implementing Procedures (EPIP)

In accordance with 10 CFR 50 Appendix E Part V and 10 CFR 50.4(b)(5)(iii), please find the following EPIP changes enclosed for the Document Control Desk (holder of Copy 165) and the NRC Region IV Administrator (holder of copies 154, 155 and 156). Please return the attached receipt confirmation forms using the enclosed pre-addressed envelopes by *February 17, 1996*.

REMOVE SECTION

EPIP Index, page 1, issued 11/27/95
EPIP-TSC-8, R8, issued 4/5/93
EPIP Index, page 3, issued 11/2/95
EPIP-RR-72, Cover Page & page 3,
R10, issued 9/8/94

INSERT SECTION

EPIP Index, page 1, issued 12/19/95
EPIP-TSC-8, R9, issued 12/19/95
EPIP Index, page 3, issued 12/20/95
EPIP-RR-72, Cover Page & page 3,
R10a, issued 9/8/94

Please note that **the changes to EPIP-TSC-8 do contain proprietary information which may not be released to the Public Document Room.** (Proprietary information includes personnel names, company phone numbers and any information which could impede emergency response.) These issues may only be used for internal NRC copies of the FCS EPIP manuals. A censored version of this procedure has been provided for the Public Document Room.

9601160349 960104
PDR ADOCK 05000285
F ----- PDR

A045
1/11 Change
NRC PDR 4/1
Emel
Non Prof


U. S. Nuclear Regulatory Commission
LIC-96-0001
Page Two

Summary of Changes

Procedure EPIP-TSC-8, "Core Damage Assessment," was revised to insert new instructions for using the computer program "PRGPASS" for estimating core damage. EPIP-TSC-8 was also revised to correct errors on Attachment 6.6, "Clad Damage Characteristics of NRC Categories of Fuel Damage." Procedure EPIP-RR-72 was revised to correct a documentable error in which the title of Attachment 6.1 was changed from "EOF" to "TSC" Field Team Specialist Checklist.

If you should have any questions, please contact me.

Sincerely,



T. L. Patterson
Division Manager
Nuclear Operations

TLP/d11

Enclosures

c: Winston & Strawn (w/o Enclosures)
L. J. Callan, NRC Regional Administrator, Region IV
L. R. Wharton, NRC Project Manager (w/o Enclosures)
W. C. Walker, NRC Senior Resident Inspector (w/o Enclosures)