Southern Nuclear Operating Company Post Office Box 1295 Birmingham, Alabama 35201 Telephone 205 868 5086



J. D. Woodard Vice President Farley Froject

Southern Nuclear Operating Company

May 6, 1992

Docket No. 50-364

U. S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, DC 20555

Joseph M. Farley Nuclear Plant - Unit 2 Special Report No. 92-002, Steam Generator Tube Plugging

Gentlemen:

Joseph M. Farley Nuclear Plant, Unit 2, Special Report No. 92-002 is being submitted in accordance with Technical Specification 4.4.6.5.a. If you have any questions, please advise.

Respectfully submitted,

J. D. Woodard

JDW/REM: map 2360

Enclosure

cc: Mr. S. D. Ebneter

Mr. S. .. Hoffman Mr. G. F. Maxwell

## Special Report 92-002, Unit 2 Steam Generator Tube Plugging

The following steam generator tube plugging report is being submitted in accordance with Technical Specification 4.4.6.5.a.

The eddy current testing results of the Unit 2 eighth refueling outage are as follows.

	S/G A	S/G B	S/G C
Plugged Tubes	11	21	10
Repaired Tubes	18	0	11
F* Tubes	16	36	165

The plugging and repair work was completed on April 22, 1992.

The complete results of the steam generator tube inservice inspection will be reported in accordance with Technical Specification 4.4.6.5.b.