



UNITED STATES
 NUCLEAR REGULATORY COMMISSION
 REGION 1
 789 ROOSEVELT ROAD
 GLEN ELLYN, ILLINOIS 60131

*OCB/OCB
(RIDS)*

MAY 06 1992

Docket No. 50-373; 50-374
 License No. NPF-11; NPF-18

Commonwealth Edison Company
 ATTN: Mr. Cordell Reed
 Senior Vice President
 Opus West III
 1400 Opus Place
 Downers Grove, IL 60515

Dear Mr. Reed:

This refers to the inspection conducted by D. Hills, C. Phillips, P. Lougheed, and G. Replogle of this office, and by J. Roman of the Illinois Department of Nuclear Safety, on February 21 through April 14, 1992. The inspection included a review of activities authorized for your LaSalle County Station, Units 1 and 2. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Based on the results of this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice of Violation (Notice). The violation is of concern because of its recurring nature.

You are required to respond to this letter and should follow the instructions specified in the enclosed Notice when preparing your response. In your response, you should document the specific actions taken and any additional actions you plan to prevent recurrence. After reviewing your response to this Notice, including your proposed corrective actions and the results of future inspections, the NRC will determine whether further NRC enforcement action is necessary to ensure compliance with NRC regulatory requirements.

Other activities were also identified to be in violation of NRC requirements during this inspection period. However, as described in the enclosed inspection report, because the violations met the criteria of the "General Statement of Policy and Procedure for NRC Enforcement Action," Enforcement Policy, 10 CFR Part 2, Appendix C, and to encourage and support licensee initiatives for self-identification and correction of violations, these violations will not be cited.

9205150008 920506
 PDR ADCK 05000373
 Q PDR

TEO


MAY 06 1992

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, the enclosures, and your response to this letter will be placed in the NRC Public Document Room.

The responses directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

for 
Brent Clayton, Chief
Reactor Projects Branch 1

Enclosures:

1. Notice of Violation
2. Inspection Reports
No. 50-373/92008(DRP);
No. 50-374/92008(DRP)

cc w/enclosure:

D. Galle, Vice President - BWR
Operations
T. Kovach, Nuclear
Licensing Manager
G. J. Diederich, Station
Manager
DCD/DCB (RIDS)
OC/LFDCB
Resident Inspectors LaSalle
Dresden, Quad Cities
Richard Hubbard
J. W. McCaffrey, Chief, Public
Utilities Division
Patricia O'Brien, Governor's
Office of Consumer Services
Licensing Project Manager, NRR
Robert Newmann, Office of Public
Counsel, State of Illinois Center
State Liaison Officer