



Commonwealth Edison
1400 Opus Place
Downers Grove, Illinois 60515

May 7, 1992

Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

ATTN: Document Control Desk

Subject: LaSalle County Station Units 1 and 2
Response to NRC Bulletin 90-01
Loss of Fill Oil in Rosemount Transmitters
NRC Docket No. 50-373 and 50-374

Reference: M.H. Richter letter to USNRC dated July 20, 1990, Response to
NRC Bulletin 90-01, Loss of Fill Oil in Rosemount Transmitters

The referenced letter provided LaSalle County Station's response to NRC Bulletin 90-01. In response to Action 2 of the bulletin, Attachment D to the referenced letter stated that during the Spring 1991 outage on Unit 1 and the Spring 1992 outage on Unit 2 the transmitters from the suspect lots would be replaced.

At this time, all the suspect lot Rosemount transmitters at LaSalle County Station have been replaced, and therefore the requirements of Action 2 of the bulletin have been fulfilled.

Please contact this office should further information be required.

Respectfully,

JoAnn M. Shields
Nuclear Licensing Administrator

cc: A.B. Davis, Regional Administrator-RIII
D. Hills, Senior Resident Inspector-LSCS

9205160010 920507
PDR ADOCK 05000373
G PDR

ZTRAIN2/156

JE39 1/0