

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

34 AUG 20 1984
August 15, 1984
3:24

BLRD-50-438/82-43
BLRD-50-439/82-29

U.S. Nuclear Regulatory Commission
Region II
Attn: Mr. James P. O'Reilly, Regional Administrator
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Dear Mr. O'Reilly:

BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2 - SPENT FUEL POOL GATES -
BLRD-50-438/82-43, BLRD-50-439/82-39 - SUPPLEMENTAL REPORT


The subject deficiency was initially reported to NRC-OIE Inspector Don Quick on June 1, 1982 in accordance with 10 CFR 50.55(e) as NCR BLN NEB 8005. This was followed by our first interim report dated July 2, 1982, our final report dated September 17, 1982, and our revised final report dated November 1, 1982. Below is our supplemental report.

As discussed with NRC-OIE Inspector P. E. Fredrickson on July 31, 1984, the date of July 31, 1984 for completion of corrective actions indicated in our final report on this matter would not be met. Because new fuel is being stored in the unit 2 spent fuel storage pool, work cannot be done as committed. Work will be done after the fuel is transferred to unit 1. The corrective action on this matter will be completed by April 20, 1986.

If you have any questions concerning this matter, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY



L. M. Mills, Manager
Nuclear Licensing

cc: Mr. Richard C. DeYoung, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

8409070136 840815
PDR ADOCK 05000438
S PDR

OFFICIAL COPY

10 IT-27