RECEIVED NIC

Arizona Public Service Company

1984 AUG 23 PM 1: 36

August 20, 1984 ANPP-30276-TDS/TRB

U. S. Nuclear Regulatory Commission Region V Creekside Oaks Office Park 1450 Maria Lane - Suite 210 Walnut Creek, CA 94596-5368

Attention: Mr. T. W. Bishop, Director

Division of Resident

Reactor Projects and Engineering Programs

Subject: Time Extension For Report - DER 84-42

A 50.55(e) Potentially Reportable Deficiency Relating To Environmentally Qualified Torque Switches Were Replaced With

Unqualified Switches.

File: 84-019-026; D.4.33.2

Reference: (A) Telephone conversation between J. Ball and T. Bradish on

June 18, 1984

(B) ANPP-29993, dated July 18, 1984 (Interim Report)

Dear Sir:

The NRC was notified of a potentially reportable deficiency in Reference (A), and an Interim Report was transmitted by Reference (B). At that time, it was estimated that a Final Report would be available by August 20, 1984.

A Final Report has been submitted to APS for review. It is expected that a Final Report will be transmitted to the NRC by September 13, 1984.

There is no new information or change to the Interim Report at this time.

Very truly yours,

E. E. Van Brunt, Jr. APS Vice President

ESVan Brunt/201

Nuclear Production ANPP Project Director

EEVB/TRB/nj

cc: See Page Two

8409070299 840820 PDR ADOCK 05000526 S PDR

16 IE-27 Mr. T. W. Bishop DER 84-42 Page Two

cc:

Richard DeYoung, Director Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

T. G. Woods, Jr.

D. B. Karner

W. E. Ide

D. B. Fasnacht

A. C. Rogers

L. A. Souza

D. E. Fowler

T. D. Shriver

C. N. Russo

J. Vorees

J. R. Bynum

J. M. Allen

J. A. Brand

A. C. Gehr

W. J. Stubblefield

W. G. Bingham

R. L. Patterson

R. W. Welcher

H. D. Foster

D. R. Hawkinson

L. E. Vorderbrueggen

R. P. Zimmerman

S. R. Frost

J. Self

M. Woods

T. J. Bloom

Records Center Institute of Nuclear Power Operations 1100 Circle 75 Parkway, Suite 1500 Atlanta, GA 30339