

May 11, 1992

Docket No. 50-369, 50-370

Mr. T. C. McMeekin
Vice President, McGuire Site
Duke Power Company
12700 Hagers Ferry Road
Huntersville, North Carolina 28078-8985

Dear Mr. McMeekin:

SUBJECT: MCGUIRE NUCLEAR STATION RESTART STEAM GENERATOR TUBE REPAIR OUTAGE

This is to confirm your commitments documented in a letter dated May 8, 1992, which provided your current plans regarding eddy current inspection for McGuire Units 1 and 2. The NRC staff has reviewed your plan and commitments in light of the ongoing discussions between the staff and Duke Power Company (DPC). The staff requests a meeting with DPC at the earliest convenient time to discuss the results of the McGuire steam generator repair outage, as well as your ongoing investigations and analyses into tube degradation phenomena at McGuire.

If you have any questions regarding this matter, please contact David Matthews at 301-504-1490.

Sincerely,

SV

Steven A. Varga, Director
Division of Reactor Projects - I/II
Office of Nuclear Reactor Regulation

cc: See next page

DISTRIBUTION
SEE NEXT PAGE

<i>DM</i> LA:PDII-3 LBerry 5/11/92	<i>DM</i> LA:PDII-3 Treed 5/11/92	<i>DM</i> DA:PDII-3 DMatthews 5/11/92	<i>DM</i> RII:AM AHerdt 5/11/92	<i>DM</i> NRR:DET JRichardson 5/11/92	<i>DM</i> ADR2 GLainas 5/11/92	<i>DM</i> DRPE SVarga 5/11/92
---	--	--	--	--	---	--

OFFICIAL RECORD COPY
Document Name: C:MCGSGT.LTR

*DFD1
110*

9205220242 920511
PDR ADOCK 05000369
PDR

138014

NRC FILE CENTER COPY

Distribution

~~Docket File~~

NRC PDR

Local PDR

PDII-3 R/F

McGuire R/F

S. Varga

G. Lainas

D. Matthews

L. Berry

T. Reed

OGC

ACRS (10)

L. Reyes, RI?