

Doc/Doc B (RDS)



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

MAY 15 1992

Docket No. 50-454
Docket No. 50-455

License Nos. NPF-37; NPF-66

Commonwealth Edison Company
ATTN: Mr. Cordell Reed
Senior Vice President
Opus West III
1400 Opus Place
Downers Grove, IL 60515

Dear Mr. Reed:

This refers to the routine safety inspection conducted by Messrs. W. J. Kropp, C. H. Brown, T. D. Reidinger, and D. E. Jones of this office from March 24, 1992 through May 5, 1992. The inspection included a review of activities at your Byron Station, Units 1 and 2. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

Sincerely,

Brent Clayton, Chief
Reactor Projects Branch 1

Enclosures:
Inspection Report Nos.

50-454/92008(DRP);
50-455/92008(DRP)

9205270134 920519
PDR ADOCK 05000454
Q PDR

250001

TEO/11

MAY 15 1992

Commonwealth Edison

2

cc w/enclosures:

M. Wallace, Vice President,
PWR Operations
T. Kovach, Nuclear Licensing
Manager
T. Schuster, Nuclear Licensing
Administrator
R. Pleniewicz, Station Manager
D. Brindle, Regulatory Assurance
Supervisor
DCD/DCB (RIDS)
OC/LFDCB
Resident Inspectors, Byron,
Braidwood, Zion
R. Hubbard
J. W. McCaffrey, Chief, Public
Utilities Division
D. Chavez, DAARE/SAFE
Licensing Project Manager, NRR
R. Newmann, Office of Public
Counsel, State of Illinois Center
R. M. Thompson, Administrator, Wisconsin
Division of Emergency Government
State Liaison Officer