




KANSAS GAS AND ELECTRIC COMPANY

GLENN L. KOESTER
VICE PRESIDENT - NUCLEAR

August 31, 1984

Mr. D.R. Hunter, Chief
Reactor Projects Branch 2
U.S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011



KMLNRC 84-156
Re: Docket No. STN 50-482
Ref: Interim Report KMLNRC 83-161 dated
12/7/83 from GLKoester, KG&E, to
JEGagliardo, NRC
Subj: Interim Status Report for Wolf Creek
10CFR50.55(e) Items

Dear Mr. Hunter:

Attached is a copy of Kansas Gas and Electric Company's status report for July and August, 1984, on 10CFR50.55(e) items. The format and purpose of this report were described in the Reference.

Please contact me or Mr. Otto Maynard of my staff if you have any questions concerning this subject.

Yours very truly,

Kent R Brown

for Glenn L. Koester
Vice President - Nuclear

GLK:bb
Attach
xc:RCDeYoung, w/a
PO'Connor, w/a
HBundy, w/a

8409140063 840831
PDR ADOCK 05000482
S PDR

IE-27
||

STATUS REPORT

On

10CFR50.55(e)/Part 21 Open Items

August 29, 1984

- I. Legend
- II. Status of KG&E Reported Items
- III. Status of SNUPPS Reported Items

I. Legend

File: QA Record File Number

Title: Title of Subject Matter

Date Reported: When Deficiency Was Initially Reported to the NRC

ST: Status

O-Open: Concern has not been resolved.

F-Final Report has been submitted but corrective action has not been completed or close-out documentation has not been through final review.

R-Ready for RRI Review - All corrective actions completed or evaluation has determined that item is not reportable pursuant to 50.55(e)/Part 21.

C-Closed: RRI has reviewed and close-out of the concern or item is N/A to WCGS.

II. Status of Significant Deficiencies

Report By KG&E

SIGNIFICANT DEFICIENCY TRACKING

FILE	TITLE	DATE REPORTED	S	NRC CLOSE	REMARKS
53564-K043	NUCLEAR COATING-SPEC A-125 (G)	80/07/25	R		PREVIOUS INTERIM REPORTS: KMLNRC-024 4/25/80 KMLNRC-034 10/25/80 KMLNRC 81-052 1/13/81 81-078 5/14/81 81-095 7/15/81 81-117 10/01/81 81-137 11/19/81 82-167 2/25/82 82-188 4/20/82 82-240 8/30/82 83-001 1/12/83 83-083 7/01/83 CURRENT STATUS: FINAL REPORT HAS BEEN SUBMITTED, KMLNRC 84-013, 02/10/84.
53564-K045	UNDERSIZED SOCKET WELDS	80/09/30	R		AWAITING NRC REVIEW
53564-K064	SEISMIC DESIGNED NON-Q PIPE HANGERS (SPECIAL SCOPE MATERIAL TRACEABILITY)	82/04/15	R		AWAITING NRC REVIEW.
53564-K065	POST ACCIDENT INSTRUMENT ERRORS	82/04/08	R		AWAITING NRC REVIEW.
53564-K068	DANIELS TEST FOR WELDING INSPECTORS	82/07/12	R		INTERIM REPORTS: KMLNRC 82-234 8/11/82 82-247 10/20/82 83-013 1/31/83 83-049 4/25/83 83-114 8/25/83 83-157 11/28/83 CURRENT STATUS: THE CURRENT STATUS WAS PROVIDED IN KMLNRC 83-157. FINAL REPORT HAS BEEN SUBMITTED. (KMLNRC 84-134, 8/6/84). AWAITING NRC REVIEW.
53564-K071	GE AKR BREAKER DEFICIENCY	82/11/09	R		FINAL REPORT HAS BEEN SUBMITTED. (KMLNRC 82-257, 12/9/82) AWAITING NRC REVIEW.

53564-K072 FAILED BATTERY CHARGER LEAD 82/12/14 R

FINAL REPORT HAS BEEN SUBMITTED. (SLNRC 83-009,
2/18/83) AWAITING NRC REVIEW.

53564-K074 DISCREPANCIES IN THE BN 83/01/31 R
SYSTEM

INTERIM REPORTS: KMLNRC 83-016 2/17/83
83-050 4/25/83
83-077 6/24/83
83-124 9/28/83

CURRENT STATUS: FINAL REPORT SUBMITTED (KMLNRC 84-
08 ON 4/24/84). AWAITING NRC REVIEW.

53564-K075 DOUBLE LOCKNUT OMITTED ON 83/01/31 R
11/1 SMALL PIPE SUPPORTS

FINAL REPORT HAS BEEN SUBMITTED. (SLNRC 83-008,
2/18/83) AND CORRECTIVE ACTION HAS BEEN IMPL-
MENTED. AWAITING NRC REVIEW.

53564-K076 INSUFFICIENT TORQUE ON 83/02/04 R
STRUCTURAL BOLTS/NUTS

INTERIM REPORTS: KMLNRC 83-121 3/03/83
83-176 6/20/83
83-116 9/09/83
83-169 12/30/83

FINAL REPORT HAS BEEN SUBMITTED (KMLNRC 84-128,
8/6/84). AWAITING NRC REVIEW.

53564-K077 U-BOLT MATERIAL TRACE- 83/02/04 R
ABILITY

FINAL REPORT HAS BEEN SUBMITTED. (KMLNRC 83-058,
5/23/83) CORRECTIVE ACTIONS HAVE BEEN IMPLEMENTED.
AWAITING NRC REVIEW.

53564-K078 COMPONENT TESTING 83/02/09 R

WITHDRAWN (KMLNRC 83-073, 6/17/83) AWAITING NRC
REVIEW.

53564-K080 GARRETT SOLENOID VALVES 83/02/11 R

FINAL REPORT HAS BEEN SUBMITTED. (KMLNRC 83-024,
3/11/83). AWAITING NRC REVIEW.

53564-K081 CONCERNING WORKMANSHIP OF 83/02/15 R
SWAGelok FITTINGS

WITHDRAWN (KMLNRC 83-109, 8/22/83) AWAITING NRC
REVIEW.

53564-K082 FOXBORO MODULES 83/02/18 R

FINAL REPORT HAS BEEN SUBMITTED. (KMLNRC 83-027,
3/18/83 AND KMLNRC 83-054, 5/12/83). AWAITING NRC
REVIEW.

53564-K083 RAY MILLER CORP. 83/02/18 R

INTERIM REPORTS: KMLNRC 83-030, 3/18/83
KMLNRC 83-092, 7/15/83

FOR WHICH A FINAL RESPONSE WAS SUBMITTED. (SLNRC 84-0049, 3/23/84). KGBE HAS WITHDRAWN THIS POTENTIAL 10CFR50.55(E). (KMLNRC 84-100, 6/28/84).

53564-K084 BRASS FITTING ON DIESEL
FIRE PUMP 83/02/21 R

FINAL REPORT HAS BEEN SUBMITTED. (KMLNRC 83-028,
3/21/83) AWAITING NRC REVIEW.

53564-K086 BOLT TORQUE ON INSTRUMENT
MOUNTS 82/02/24 R

FINAL REPORT HAS BEEN SUBMITTED. (KMLNRC 83-078,
6/24/83) AWAITING NRC REVIEW

53564-K087 GA TECHNOLOGIES RN-23 83/02/24 R

FINAL REPORT HAS BEEN SUBMITTED. (SLNRC 83-031,
5/27/83) AWAITING NRC REVIEW.

53564-K088 WELDS ON BERGEN-PATERSON
SUPPORTS 83/02/24 R

INTERIM REPORTS: KMLNRC 83-034, 3/25/83
83-060, 5/26/83
83-093, 7/18/83
83-138, 10/21/83

CURRENT STATUS: NO SIGNIFICANT STRUCTURAL DEFICIENCIES HAVE BEEN IDENTIFIED.
WITHDRAWN (KMLNRC 84-032 ON 3/16/84) AWAITING NRC REVIEW.

53564-K089 GE AKR CIRCUIT BREAKERS 82/02/28 R

FINAL REPORT HAS BEEN SUBMITTED. (SLNRC 83-023,
4/28/83) AWAITING NRC REVIEW.

53564-K090 POWER CONVERSION PRODUCTS
BATTERY CHARGERS 83/03/09 R

INTERIM REPORTS: KMLNRC 83-040, 4/08/83
83-087, 7/11/83
83-126, 10/03/83

CURRENT STATUS: FINAL REPORT HAS BEEN SUBMITTED
(KMLNRC 84-129, 8/5/84). AWAITING NRC REVIEW.

53564-K091 STRUCTURAL STEEL WELDS 83/03/23 R

WITHDRAWN: AWAITING NRC REVIEW (KMLNRC 83-139,
10/21/83)

53564-K092 STITCH WELDING ON ELECTRICAL
RACEWAYS AND CONDUIT 83/03/25 R

WITHDRAWN: AWAITING NRC REVIEW (KMLNRC 83-047,
4/22/83.)

53564-K093 LOOSE PARTS FOUND IN STEAM
GENERATORS 83/04/26 R

FINAL REPORT HAS BEEN SUBMITTED (KMLNRC 83-105,
8/12/83) AWAITING NRC REVIEW.

53564-K094 USE OF TEFLON IN THE POWER
BLOCK 83/05/04 R

FINAL REPORT HAS BEEN SUBMITTED (KMLNRC 83-066,
6/3/83) AWAITING NRC REVIEW.

53564-K097 CUTLER-HAMMER PUSH BUTTON
SWITCHES 83/06/09 R

INTERIM REPORTS: KMLNRC 83-085, 7/08/83
83-123, 9/28/83

CURRENT STATUS:
FINAL REPORT SUBMITTED (KMLNRC 84-057 ON 4/9/84)

53564-K099	BERGEN-PATERSON WELD BEAM ATTACHMENTS	83/06/17 R	INTERIM REPORTS: KMLNRC 83-089, 7/15/83 83-141, 10/28/83 CURRENT STATUS: WITHDRAWN (KMLNRC 84-021 ON 2/22/84). AWAITING NRC REVIEW
53564-K100	GUYON 1/2 INCH SOCKET COUPLING	83/06/17 R	WITHDRAWN (KMLNRC 83-135, 10/14/83) AWAITING NRC REVIEW.
53564-K101	VULKENE SUPREME CABLE	83/06/20 O	INTERIM REPORTS: KMLNRC 83-095, 7/20/83 83-125, 9/28/83 83-151, 11/23/83 CURRENT STATUS: KMLNRC 83-151 PROVIDED CURRENT STATUS - ANTICIPATE FINAL REPORT BY 9/15/84
53564-K103	SWAY STRUT WASHERS	83/07/15 O	INTERIM REPORTS: KMLNRC 83-104, 8/12/83 83-143, 11/03/83 CURRENT STATUS: ANTICIPATE FINAL REPORT BY 9/15/84
53564-K104	AUXILIARY FEEDWATER PUMP SHAFT	83/07/18 R	FINAL REPORT HAS BEEN SUBMITTED (KMLNRC 83-108, 8/17/83) AWAITING NRC REVIEW
53564-K106	GOULD-RUNDELL HANDSWITCHES	83/08/24 F	FINAL REPORT HAS BEEN SUBMITTED (SLNRC 84-028 ON 2/9/84). SUPPLEMENTAL INFORMATION WAS PROVIDED. (SLNRC 84-0067, 4/13/84 AND SLNRC 84-103, 7/20/84). AWAITING ISSUANCE OF PMP'S.
53564-K107	PSA SNUBBERS	83/09/13 R	FINAL REPORT HAS BEEN SUBMITTED (SLNRC 83-0058, 11/9/83) AWAITING NRC REVIEW.
53564-K108	EXPOSED THREADS ON SEAL WELDED CONNECTIONS	83/10/12 R	INTERIM REPORTS: KMLNRC 83-146, 11/09/83 CURRENT STATUS: FINAL REPORT HAS BEEN SUBMITTED (KMLNRC 84-011 ON 3/16/84) AWAITING NRC REVIEW.
53564-K109	CRACKED EDGE CONNECTORS ON WESTINGHOUSE 7300 PROCESS SYSTEM	83/10/25 R	INTERIM REPORTS: KMLNRC 83-153, 11/23/83 CURRENT STATUS: WITHDRAWN (KMLNRC 84-036 ON 3/16/84) AWAITING NRC REVIEW.
53564-K110	IMPROPER FITTING ON MSIV	83/10/25 R	INTERIM REPORTS: KMLNRC 83-152, 11/23/83 CURRENT STATUS: FINAL REPORT HAS BEEN SUBMITTED (KMLNRC 84-133, 8/6/84). AWAITING NRC REVIEW.
53564-K111	HVAC	83/11/10 R	30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 83-163, 12/9/83) FINAL REPORT WAS SUBMITTED. (KMLNRC 83-137, 8/8/84). AWAITING NRC REVIEW.
53564-K112	POLAR CRANE TESTING	83/11/18 O	30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 83-165, 12/16/83) (POTENTIAL 50.55CE.) ALL TESTING SHOULD BE COMPLETED BY MID AUGUST 1984. FINAL

53564-K113 CABLE TERMINATION LUGS 83/11/18 R
 30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 83-164, 12/16/83) WITHDRAWN (KMLNRC 84-90 ON 6/15/84).

53564-K114 I BEAMS 83/12/01 O
 30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 83-170, 12/30/83) (POTENTIAL 50.55(E).) FINAL REPORT ANTICIPATED BY 9/15/84

53564-K115 CODE WELDING 83/12/07 R
 30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 84-02 ON 1/6/84) WITHDRAWN (KMLNRC 83-042 ON 3/16/84) AWAITING NRC REVIEW.

53564-K116 PIPE SCHEDULE 83/12/13 O
 30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 84-05 ON 1/12/84) AWAITING COMPLETION OF CONSTRUCTOR INSPECTIONS OF TWO SYSTEMS. ANTICIPATING FINAL REPORT BY 9/15/84.

53564-K117 POP PULSATION DAMPERS 83/12/21 R
 30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 84-007 ON 1/19/84) WITHDRAWN (KMLNRC 83-37 ON 3/16/84) AWAITING NRC REVIEW.

53564-K118 FIELD PROCUREMENT 84/01/03 O
 30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 84-011 ON 02/02/84) AWAITING COMPLETION OF EVALUATION. (POTENTIAL 10CFR50.55(E).) ANTICIPATE FINAL REPORT BY 9/15/84

53564-K119 BUTTERFLY VALVES 84/01/10 R
 30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 84-014 ON 02/09/84) FINAL REPORT WAS SUBMITTED (KMLNRC 84-132, 8/6/84). AWAITING NRC REVIEW.

53564-K120 FUSION WELDED PIPEL 84/01/20 O
 30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 84-018 ON 02/17/84) ANTICIPATE FINAL REPORT 9/15/84

53564-K121 LIMITORQUE OPERATORS 84/02/03 O
 30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 84-024 ON 3/7/84) AWAITING COMPLETION OF EVALUATION. (POTENTIAL 10CFR 50.55(E).) ANTICIPATE FINAL REPORT IN SEPTEMBER.

53564-K122 CHECK VALVES 84/02/06 O
 30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 84-027 ON 3/7/84). ANTICIPATE FINAL REPORT 9/15/84

53564-K123 TEN INCH GATE VALVES 84/02/27 R
 30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 84-44 ON 3/26/84) WITHDRAWAL WAS SUBMITTED (KMLNRC 84-131, 8/6/84) AWAITING NRC REVIEW.

53564-K124 LOAD SHEDDER EMERGENCY LOAD 84/02/27 R
 SEQUENCER
 FINAL REPORT SUBMITTED (KMLNRC 84-52 ON 3/30/84) AWAITING NRC REVIEW.

53564-K125 PORV RELAYS 84/03/02 R
 FINAL REPORT SUBMITTED (KMLNRC 84-0064 ON 4/13/84) AWAITING NRC REVIEW.

53564-K126 DIESEL GENERATION LUBE OIL 84/03/09 0
KEEP WARM PUMP
30 DAY INTERIM REPORT HAS BEEN SUBMITTED (KMLNRC 84-56 ON 4/5/84) AWAITING COMPLETION OF EVALUATION (POTENTIAL 10CFR 50.55(E).) ANTICIPATE FINAL REPORT IN SEPTEMBER.

53564-K127 VALCOR WIRING 84/03/15 F
FINAL REPORT SUBMITTED (SLNRC 84-65 ON 4/13/84) AWAITING COMPLETION OF REWORK. ANTICIPATE COMPLETION OF REWORK BY 9/15/84

53564-K128 FAN MECHANICAL INTERLOCKS 84/03/16 0
30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 84-61 ON 4/11/84) AWAITING COMPLETION OF EVALUATION. (POTENTIAL 10CFR 50.55(E).) ANTICIPATE FINAL REPORT BY 9/15/84

53564-K129 SAFETY INJECTION ACCUMULATORS 84/03/19 R
30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 84-63 ON 4/19/84) WITHDRAWN (KMLNRC 84-089 ON 6/15/84).

53564-K130 DISCHARGE PULSATION DAMPER 84/03/19 R
30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 84-65 ON 4/18/84) WITHDRAWAL WAS SUBMITTED (KMLNRC 84-111, 7/11/84). AWAITING NRC REVIEW.

53564-K131 AFM TURBINE RELAY 84/03/19 R
FINAL REPORT SUBMITTED (KMLNRC 84-64 ON 4/18/84) SUPPLEMENTAL INFORMATION WAS SUBMITTED (KMLNRC 84-136, 8/8/84) AWAITING NRC REVIEW.

53564-K132 SEISMIC POSITIONER PLATES ON DS416 REACTOR TRIP BREAKERS 84/03/27 0
30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 84-071 ON 4/26/84) ANTICIPATE FINAL REPORT BY 9/15/84

53564-K133 CONTAINMENT SPRAY PUMP ROOM FLOODING 84/03/27 0
30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 84-072 ON 4/26/84) AWAITING COMPLETION OF EVALUATION.

53564-K134 LIMITORQUE SHEARED PINION KEY 84/04/19 R
FINAL REPORT HAS BEEN SUBMITTED, (SLNRC 84-078, 05/09/84). AWAITING NRC REVIEW.

53564-K135 BARTON 752 TRANSMITTERS 84/04/24 0
30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 84-078 ON 05/23/84). AWAITING COMPLETION OF EVALUATION. ANTICIPATE FINAL REPORT BY 9/15/84

53564-K136 ISOLATION RELAY CARDS 84/04/26 R
30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 84-081 ON 05/25/84). FINAL REPORT WAS SUBMITTED (KMLNRC 84-140, 8/8/84). AWAITING NRC REVIEW.

53564-K137 REACTOR VESSEL LEVEL INDICATION SYSTEM 84/04/27 R
30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 84-082 ON 05/25/84). FINAL REPORT WAS SUBMITTED (KMLNRC 84-138, 8/8/84). AWAITING NRC REVIEW.

53564-K138 DIESEL TURBOCHARGER	84/05/04 0	30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 84-083 ON 06/01/84). AWAITING COMPLETION OF EVALUATION. ANTICIPATE FINAL REPORT IN SEPTEMBER.
53564-K139 TPI LEAD AUDITOR	84/05/24 0	30 DAY INTERIM REPORT WAS SUBMITTED. (KMLNRC 84-098, 6/21/84) ANTICIPATE FINAL REPORT IN SEPTEMBER
53564-K140 3-HOUR FIRE DOORS	84/05/25 F	FINAL REPORT WAS SUBMITTED (KMLNRC 84-097, 6/21/84). AWAITING COMPLETION OF REWORK.
53564-K141 MICROBIOLOGICALLY INFLUENCED CORROSION	84/06/01 0	30 DAY INTERIM REPORT WAS SUBMITTED. (KMLNRC 84-106, 6/29/84). REWORK IN PROGRESS. ANTICIPATE FINAL REPORT IN SEPTEMBER.
53564-K142 FISCHER VALVE WITH BETTIS ACTUATOR	84/06/13 R	FINAL REPORT WAS SUBMITTED (KMLNRC 84-116, 7/13/84) AWAITING NRC REVIEW.
53564-K143 ASME COMPONENT REMOVAL	84/06/13 0	30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 84-115, 7/11/84). UNDER EVALUATION. ANTICIPATE CLOSURE IN SEPTEMBER.
53564-K144 CONTAINMENT SPRAY PUMP	84/06/14 R	WITHDRAWAL WAS SUBMITTED. (KMLNRC 84-114, 7/11/84) AWAITING NRC REVIEW.
53564-K145 LAUNDRY AND HOT SHOWER CHARCOAL ADSORBER	84/06/18 R	WITHDRAWAL WAS SUBMITTED. (KMLNRC 84-112, 7/11/84) AWAITING NRC REVIEW.
53564-K146 LIMITORQUE SB-2-80 ACTUATOR GEAR DAMAGE	84/04/19 0	30 DAY INTERIM REPORT WAS SUBMITTED (SLNRC 84-90 ON 06/01/84). INTERIM REPORT WAS SUBMITTED (SLNRC 84-106, 7/20/84) AWAITING COMPLETION OF TESTING AND REWORK. ANTICIPATE CLOSURE IN SEPTEMBER.
53564-K147 LUBE OIL SYSTEM PIPING	84/07/17 0	30 DAY INTERIM REPORT WAS SUBMITTED (KMLNRC 84-147, ON 8/17/84) AWAITING COMPLETION OF ENGINEERING EVALUATION. ANTICIPATE CLOSURE IN SEPTEMBER.
53564-K148 RCS RTD CALIBRATION DATA	84/08/01 0	30 DAY INTERIM REPORT WILL BE SUBMITTED BY 8/31/84. UNDER INITIAL EVALUATION.
53564-K149 INCORE THERMOCOUPLES	84/08/06 0	30 DAY INTERIM REPORT WILL BE SUBMITTED BY 9/5/84. UNDER INITIAL EVALUATION.
53564-K150 TC/CCM ALARM RELAYS	84/08/21 0	30 DAY INTERIM REPORT BY 9/20/84
53564-K151 MECHANICAL SNUBBERS	84/08/23 0	30 DAY INTERIM REPORT BY 9/21/84

III. Status of Significant Deficiencies

Reported By SNUPPS Staff

Note: Some of the items in this file are not applicable to
Wolf Creek.

SIGNIFICANT DEFICIENCY TRACKING

FILE	TITLE	DATE REPORTED	S	NRC CLOSE	REMARKS
55780-K002	ECCS FINAL ACCEPTANCE CRITERIA- REVISED ACCIDENT ANALYSIS	76/05/05	R		FINAL REPORT WAS SUBMITTED SLNRC 6-6, 9/3/76; AWAITING NRC REVIEW.
55780-K007	RUSKIN FIRE DAMPERS	80/01/18	R		FINAL REPORT HAS BEEN SUBMITTED SLNRC 80-24, 5/16/80. AWAITING NRC REVIEW.
55780-K009	CHECK VALVE CLOSURE EXCESSIVE PRESSURE	80/06/30	R		WITHDRAWN SLNRC 80-32, 6/30/80. AWAITING NRC REVIEW.
55780-K010	QUALIFICATION OF CONTROL SYSTEMS	79/08/30	R		FINAL REPORT HAS BEEN SUBMITTED, SLNRC 80-6, 2/5/80 AWAITING NRC REVIEW.
55780-K011	PRESSURIZED ANCHOR BOLT SUPPORTS	79/03/23	R		FINAL REPORT HAS BEEN SUBMITTED, SLNRC 79-6, 5/1/79 AWAITING NRC REVIEW.
55780-K012	ROD DROP SAFETY ANALYSIS	79/03/29	R		WITHDRAWN SLNRC 79-5, 4/26/79. AWAITING NRC REVIEW
55780-K019	CHARGING PUMP OPERATION FOLLOWING SECONDARY SIDE HIGH ENERGY LINE RUPTURE W CENTRIFUGAL	80/05/08	R		FINAL REPORT HAS BEEN SUBMITTED, SLNRC 82-42, 10/29/82. AWAITING NRC REVIEW.
55780-K020	UNDETECTABLE FAILURE IN ENGINEERED SAFETY FEATURES ACTUATION SYSTEM RUPTURE	79/12/06	R		FINAL REPORT HAS BEEN SUBMITTED, SLNRC 80-12, 3/20/80 AND SLNRC 80-19, 4/19/80. AWAITING NRC REVIEW.
55780-K024	5 INCH ISOLATION VALVES (w)	80/10/30	R		FINAL REPORT HAS BEEN SUBMITTED, SLNRC 82-038, 9/3/82. AWAITING NRC REVIEW.
55780-K028	BERGEN-PATTERSON SIZE NO. 6 AND SIZE NO. 15 SWAY STUTS	81/10/09	R		WITHDRAWN SLNRC 81-128, 12/14/81. AWAITING NRC REVIEW.
55780-K029	LIMITORQUE SHEARED PINION KEYS IN MOTOR OPERATORS	82/08/04	R		WITHDRAWN: SLNRC 83-C12, 3/3/83. AWAITING NRC REVIEW.
55780-K030	UNDETECTABLE FAILURE IN ON-LINE CIRCUITS FOR RELAYS	82/08/04	R		INTERIM REPORTS: SLNRC 82-0036, 9/3/82 83-0013, 3/3/83 83-0049, 9/2/83 CURRENT STATUS: FINAL REPORT HAS BEEN SUBMITTED, SLNRC 84-0020, 02/02/84. AWAITING NRC REVIEW.
55780-K031	VALVE POSITION INDICATION FOR W GATE VALVES	82/12/22	R		FINAL REPORT HAS BEEN SUBMITTED, SLNRC 83-032, 5/31/83. AWAITING NRC REVIEW.
55780-K032	ANCHOR DARLING CHECK VALVES	83/03/23	R		FINAL REPORT HAS BEEN SUBMITTED, SLNRC 83-020,

55780-K031 REACTOR TRIP SWITCHGEAR 83/04/21 F

FINAL REPORT HAS BEEN SUBMITTED, SLNRC 83-028,
5/23/83. AWAITING COMPLETION OF RECORDS.

55780-K034 W 7500 PROCESS RACKS 83/06/02 0

INTERIM REPORTS: SLNRC 83-0039, 7/21/83
AWAITING COMPLETION FO SEISMIC TESTING OF REPLACEMENT CARDS.

55780-K035 YARWAY VALVES 83/06/17 R

FINAL REPORT HAS BEEN SUBMITTED, SLNRC 83-037,
7/18/83 AND SLNRC 83-043, 7/29/83. AWAITING
MRC REVIEW.

55780-K036 EXCESSIVE VOLTAGE DROF CON- 83/06/23 F
TROL CABLES

FINAL REPORT HAS BEEN SUBMITTED, SLNRC 83-040,
7/22/83. AWAITING COMPLETION OF CORRECTIVE ACTION.

55780-K037 HANGER CLASSIFICATION 83/10/23 R

INTERIM REPORT: SLNRC 83-0080 11/22/83
CURRENT STATUS: FINAL REPORT HAS BEEN SUBMITTED,
SLNRC 84-006, 01/20/84. AWAITING MRC REVIEW.

55780-K038 LIMITORQUE LIMIT SWITCH 83/11/16 R
ROTORS

30 DAY INTERIM REPORT WAS SUBMITTED (SLNRC 83-0064
12/22/83) (POTENTIAL 50-55(E).) FINAL REPORT HAS
BEEN SUBMITTED (SLNRC 84-0064, 4/13/84). AWAITING
MRC REVIEW.

***** END REPORT *****