Arizona Public Service Company

August 29, 1984 ANPP-30355-TDS/TRB

U. S. Nuclear Regulatory Commission Region V Creekside Oaks Office Park 1450 Maria Lane - Suite 210 Walnut Creek, CA 94596-5368

Attention: Mr. T. W. Bishop, Director
Division of Resident
Reactor Projects and Engineering Programs

Subject: Time Extension For Report - DER 84-35
A 50.55(e) Potentially Reportable Deficiency Relating To
Setpoint Potentiometers In The PPS Drift Outside Of Tolerance.
File: 84-019-026; D.4.33.2

Reference: (A) Telephone conversation between P. Narbut and T. Bradish on May 17, 1984

(B) ANPP-29732, dated June 12, 1984 (Interim Report)

Dear Sir:

The NRC was notified of a potentially reportable deficiency in Reference (A), and an Interim Report was transmitted by Reference (B). At that time, it was estimated that a Final Report would be available by August 31, 1984.

Due to the extensive investigation and evaluation required, it is now expected that this information will be finalized by September 28, 1984, at which time a complete report will be submitted.

There is no new information or change to the Interim Report at this time.

Very truly yours,

E. E. Van Brunt, Jr.

APS Vice President

Nuclear Production

ANPP Project Director

REGION VILLE

EEVB/TRB/nj

cc: See Page Two

97:1 Nd 7- das 4861

HECEIAED

8409170202 840829 PDR ADDCK 05000528 S PDR 10 IE-27 Mr. T. W. Bishop DER 84-35 Page Two

cc:

Richard DeYoung, Director Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

T. G. Woods, Jr.

D. B. Karner

W. E. Ide

D. B. Fasnacht

A. C. Rogers

L. A. Souza

D. E. Fowler

T. D. Shriver

C. N. Russo

J. Vorees

J. R. Bynum

J. M. Allen

J. A. Brand

D. Canady

A. C. Gehr

W. J. Stubblefield

W. G. Bingham

R. L. Patterson

R. W. We'cher

H. D. Foster

D. R. Hawkinson

L. E. Vorderbrueggen

R. P. Zimmerman

S. R. Frost

L. Clyde

M. Woods

T. J. Bloom

Records Center Institute of Nuclear Power Operations 1100 Circle 75 Parkway, Suite 1500 Atlanta, GA 30339