

SEP 12 1984

MEMORANDUM FOR: J. A. Olshinski, Director
Division of Reactor Safety
Region II

FROM: Gary G. Zech, Chief
Vendor Program Branch
Division of Quality Assurance, Safeguards,
and Inspection Programs
Office of Inspection and Enforcement

SUBJECT: MACHINING ERROR ON LOWER STEM, PLUG AND LOCK PIN
OF A WKM DECAY HEAT COOLER OUTLET VALVE FURNISHED
BY BABCOCK & WILCOX FOR USE ON BELLEFONTE UNIT 2
(VITS 81-050)

The above item is closed without action based on Babcock & Wilcox's letter dated May 11, 1981, to the NRC, in which they indicate the subject deficiency is an isolated case without generic implications.

If you have any questions concerning this matter, please contact Mr. R. E. Oiler (FTS 492-9634).

ORIGINAL SIGNED BY:
GARY G. ZECH

Gary G. Zech, Chief
Vendor Program Branch
Division of Quality Assurance, Safeguards,
and Inspection Programs


DISTRIBUTION:


DMB:IE:09
VPB Reading
JGPartlow
EMerschoff
Roller
VITS 81-050

50-439

VPB:DQASIP
Roller:sam
9/5/84

REC


EC/VPB:DQASIP
EMerschoff
9/6/84


EC/VPB:DQASIP
GGZech
9/7/84

8409170207 840912
PDR ADOCK 05000439
S PDR

IE09

1/0