AN REQUISION OF THE STATE OF TH

UNITED STATES

## NUCLEAR REGULATORY COMMISSION

REGIONIV

B11 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-8064

JUN 4 1992

Docket Nos. 50-498

50-499

License Nos. NPF-76

NPF-80

Houston Lighting & Power Company ATTN: Donald P. Hall, Group Vice President, Nuclear P.O. Box 1700 Houston, Texas 77251

Gentlemen:

SUBJECT: NRC INSPECTION REPORT 50-498/92-10; 50-499/92-10

This refers to the inspection conducted by Mr. Lamen M. Terc of this office during April 6-9, 1992. The inspection included a review of activities authorized for your South Texas Project, Units 1 and 2 facility. At the conclusion of the inspection, the findings were discussed with Mr. W. Kinsey and other members of your staff identified in the inspection report.

Areas examined during the inspection included a review of emergency detection and classification, protective action decisionmaking, shift staffing, and augmentation of the emergency response organization. Within these areas, the inspection consisted of selective examination of procedures and representative records, interviews with personnel, and observations of activities in progress. The inspection findings are documented in the enclosed inspection report.

Based on the results of this impection, no violations or deviations were identified. However, the inspector was not able to locate licensee records which demonstrated the effectiveness of the callout methods used after July 11, 1991, for staff augmentation. So that the NRC staff can make an appropriate enforcement decision since this was the subject of a previous Notice of Violation, we need additional information. The matters related to this request are discussed in paragraph 5 of the enclosed inspection report and were discussed in a telephone conversation on May 14, 1992, between Mr. Thomas E. Underwood of your staff and Mr. Nemen Terc of this office. You are requested to provide us with your basis for assuring that you meet the Emergency Plan staff augmentation requirements. We request this information be provided within 30 days from the date of this letter.

We also examined actions you have taken with regard to previously identified inspection findings. The status of these items is identified in paragraph 2 of the enclosed report.

9206100002 92060498 PDR ADDCK 05000498 Houston Lighting and -2- JUN 4 1992

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be placed in the Public Document Room.

If you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

A. Bill Beach, Director Division of Reactor Projects

Enclosure: NRC Inspection Report 50-498/92-10; 50-499/92-10

cc W/enclosure:
Houston Lighting & Power Company
ATTN: William J. Jump, Manager
Nuclear Licensing
P.O. Box 289
Wadsworth, Texas 77483

City of Austin Electric Utility Department ATTN: J. C. Lanier/M. B. Lee P.O. Box 1088 Austin, Texas 78767

City Public Service Board ATTN: R. J. Costello/M. T. Hardt P.O. Box 1771 San Antonio, Texas 78296

Newman & Holtzinger, P. C. ATTN: Jack R. Newman, Esq. 1615 L Street, NW Washington, D.C. 20036

Central Prwer and Light Company ATTN: D. . Ward/T. M. Puckett P.O. Box 2121 Corpus Christi, Texas 78403

INPO Records Center 1100 Circle 75 Parkway Atlanta, Georgia 30339-3064 Housion Lighting and Power Company

Mr. Joseph M. Hendrie 50 Bellport Lane Bellport, New York 11713

Bureau of Radiation Control State of Texas 1101 West 49th Street Austin, Texas 78756

Judge, Matagorda County Matagorda County Courthouse 1700 Seventh Street Bay City, Texas 77414

Licensing Representative Houston Lighting & Power Company Suite 610 Three Metro Center Bethesda, Maryland 20814

Houston Lighting & Power Company ATTN: Rufus S. Scott, Associate General Counsel P.O. Box 61867 Houston, Texas 77208

Chief, Technological Hazards Branch FEMA Region 6 Federal Center 800 North Loop 288 Denton, Texas 76201-3698 -bcc to DMB (1E01)

bcc distrib. by RIV:

R. D. Martin DRP Lisa Shea, RM/ALF (4503) FIPS File Project Engineer (DRP/D) DRS L. J. Callan, DRSS B. Murray, FIPS C. A. Hackney, SLO Resident Inspector Section Chief (DRP/O) MIS System RSTS Operator RIV File R. Bachmann, OGC J. P. Jaudon, DRSS N. M. Terc, FIPS

\*RIV:FIPS NMTerc:nh / /92 \*C:FIPS BMurray / /92 D:DR. D. LJCallan 1/2/92

D: DEP | ABB 3364 G/3 /92 bcc to DMB (IEO1)

bcc distrib. by RIV:

R. D. Martin DRP Lisa Shea, RM/ALF (4503) FIPS File Project Engineer (DRP/D) DRS L. J. Callan, DRSS B. Murray, FIPS C. A. Hackney, SLO Resident Inspector Section Chief (DRP/D) MIS System RSTS Operator RIV File R. Bachmann, OGC J. P. Jaudon, DRSS N. M. Terc, FIPS

\*RIV:FIPS NMTerc:nh / /92 \*C:FIPS BMurray / /92 D:DRES LJCallan 6/2/92 D: DEP | ABB Justo G/3 /92