



SAFEGUARDS INFORMATION

UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION II
101 MARIETTA STREET, N.W.
ATLANTA, GEORGIA 30323

Report Nos.: 50-348/92-13 and 50-364/92-13

Licensee: Southern Nuclear Operating Company, Inc.
600 North 18th Street
Birmingham, AL 35291-0400

Docket Nos.: 50-348 and 50-364 License Nos.: NPF-2 and NPF-8

Facility Name: Farley 1 and 2

Inspection Conducted: April 27 - May 1, 1992

Inspector: *D. Thompson* 6-4-92
D. Thompson, Safeguards Inspector Date Signed

Accompanying Personnel: D. McGuire

Approved by: *William J. Tobin* 6/4/92
D. R. McGuire, Chief Date Signed
Safeguards Section
Nuclear Materials Safety and Safeguards Branch
Division of Radiation Safety and Safeguards

SUMMARY

Scope:

This routine, unannounced inspection was conducted in the areas of Protected and Vital Area Access Control, Security Training and Qualification, Power Supply, Safeguards Contingency Plan, and Protection of Safeguards Information.

Results:

In the areas inspected, one violation was identified. The protected and vital area access controls were found to be in accordance with regulatory requirements. Security power supply was reviewed on April 29, and found to be in accordance with regulatory requirements. It was noted while reviewing Training and Qualification (T&Q) Plan requirements that personnel responsible for conducting annual requalification training were not requiring the officers to demonstrate their capabilities on certain tasks as required which is a violation of regulatory requirements. Further it was noted that the drills for the past year were shallow and did not test the capability of the security force to respond to the threat as defined in 10 CFR Part 73.

SAFEGUARDS INFORMATION

Document transmitted hereby
is unclassified, including
information. When separate from
enclosures, this document is unclassified.