Georgia Power Continany 40 Inverness Center Parkway Post Office Box 1295 Birmingham, Alabama 35201 Telaphone 205 877-7122

C. K. McCoy Vice President, Nuclear Vogtis Project

June 10, 1992



the southern electric system

ELV-03817 001698

Docket Nos. 50-424 50-425

Director, Office of Resource Management U. S. Nuclear Regulatory Commission Washington, D. C. 20555

Gentlemen:

VOGTLE ELECTRIC GENERATING PLANT MONTHLY OPERATING REPORTS

Enclosed are the May 1992 monthly operating reports for Vogtle Units 1 and 2. These reports are submitted in accordance with Technical Specification 6.8.1.5.

Sincerely,

C. K. McCoy

CKM/JLL/gmb

Enclosures:

Monthly Operating Report - VEGP Unit 1
 Monthly Operating Report - VEGP Unit 2

3. Challenges to PORV or Safety Valves - VEGP Units 1 and 2

xc: Georgia Power Company

Mr. W. B. Shipman Mr. M. Sheibani

NORMS

U. S. Nuclear Regulatory Commission

Mr. S. D. Ebneter, Regional Administrator

Mr. D. S. Hood, Licensing Project Manager, NRR

Mr. B. R. Bonser, Senior Resident Inspector, Vogtle

Document Control Desk

160005

9206150489 920531 PDR ADDCK 05000424 R PDR TERA 11

ENCLOSURE 1

VOGTLE ELECTRIC GENERATING PLANT - UNIT 1 MONTHLY OPERATING REPORT FOR MAY 1992

TABLE OF CONTENTS

NARRATIVE REPORT	Page V1-1
OPERATING DATA REPORT	Page V1-2
AVERAGE DAILY POWER LEVEL	Page V1-3
UNIT SHUTDOWNS AND POWER REDUCTIONS	Page V1-4

NARRATIVE REPORT

DOCKET NO. 50-424

DATE: JUNE 5, 1992

COMPLETED BY: G. L. HOOPER

TELEPHONE: (706) 826-4104

```
MAY 01 00:00 UNIT 1 AT 100% POWEP WITH NO OPERATIONAL PROBLEMS.

MAY 05 23:25 UNIT 1 BEGAN POWEY REDUCTION TO 90% TO REPAIR VALVE

MAY 06 23:30 UNIT 1 RETURNED TO 100% POWER.

MAY 14 04:22 UNIT 1 BEGAN SISSITION DUE TO HIGH RCS LEAKAGE

MAY 14 08:51 UNIT 1 MAIN TURBINE OFF LINE.

MAY 14 09:03 UNIT 1 ENTERED MODE 2.

MAY 14 19:34 UNIT 1 ENTERED MODE 4.

MAY 14 19:34 UNIT 1 ENTERED MODE 5.

MAY 19 18:06 UNIT 1 ENTERED MODE 4.

MAY 20 11:51 UNIT 1 ENTERED MODE 3.

MAY 21 02:31 UNIT 1 ENTERED MODE 2.

MAY 21 03:47 UNIT 1 CRIT.CAL..

MAY 22 07:05 UNIT 1 GENERATOR TIED TO GRID.

MAY 23 00:00 UNIT 1 RETURNED TO 100% POWER.
```

MAY 31 23:59 UNIT 1 AT 100% POWER WITH NO OPERATIONAL PROBLEMS.

OPERATING DATA REPORT

DOCKET NO. 50-424

DATE: JUNE 5, 1992 COMPLETED BY: G. L. HOOPER

TELEPHONE: (706) 526-4104

OPERATING STATUS

1. UNIT NAME:	VEGP UNIT 1
2. REPORT PERIOD:	MAY 1992
3. LICENSED THERMAL POWER (MWI):	3411
4. NAMEPLATE RATING (GROSS MWe):	1215
5. DESIGN ELECTRICAL RATING (NET MWe):	1101
6. MAXIMUM DEPENDABLE CAPACITY (GROSS MWe):	1159
7. MAXIMUM DEPENDABLE CAPACITY (NET MWe):	1105
8. IF CHANGES OCCUR IN CAPACITY RATINGS	N/A

(ITEMS 3 THROUGH 7) SINCE LAST REPORT, GIVE REASONS:

NO RESTRICTIONS N/A

9. POWER LEVEL TO WHICH RESTRICTED, IF ANY (NET MWe): 10. REASONS FOR RESTRICTION, IF ANY:

	THIS MONTH	YR. TO DATE	CUMULATIVE
11. HOURS IN REPORTING PERIOD:	744	3647	43848
12. NUMBER OF HOURS REACTOR WAS CRITICAL:	581.3	3484.3	37123.2
13. REACTOR RESERVE SHUTDOWN HOURS:	0.0	0.0	0.0
14. HOURS GENERATOR ON-LINE:	553.8	3456.8	36227.8
15. UNIT RESERVE SHUTDOWN HOURS:	0.0	0.0	0.0
16. GROSS THERMAL ENERGY GENERATED (MWH):	1866712	11541298	120128684
17. GROSS ELEC. ENERGY GENERATED (MWH):	631992	3946937	40116970
18. NET ELEC. ENERGY GENERATED (MWH):	599072	3771867	38029300
19. REACTOR SERVICE FACTOR	78.1%	95.5%	84.7%
20. REACTOR AVAILABILITY FACTOR	78.1%	95.5%	84.7%
21. UNIT SERVICE FACTOR:	74.4%	94.8%	82.6%
22. UNIT AVAILABILITY FACTOR:	74.4%	94.8%	82.6%
23. UNIT CAPACITY FACTOR (USING MDC NET):	72.9%	93.6%	79.8%
24. UNIT CAPACITY FACTOR (USING DER NET):	73.1%	93.9%	78.8%
25. UNIT FORCED OUTAGE RATE:	25.6%	5.2%	6.9%
DE CUITTOURIS COLIFOURED OVER THE MEYT CHOM	LID CTUDE DATE AND	DUDATION OF EA	OLS

26. SHUTDOWNS SCHEDULED OVER THE NEXT 6 MONTHS (TYPE, DATE, AND DURATION OF EACH). NONE

27. IF SHUTDOWN AT END OF REPORT PERIOD, ESTIMATED DATE OF STARTUP:

N/A

UNIT 1 AVERAGE DAILY POWER LEVEL DOCKET NO. 50-424
DATE: JUNE 5, 1992
COMPLETED BY: G. L. HOOPER
TELEPHONE: (706) 826-4104

YAC		Net MW	
- 1	immelimateonomemore	1112	*
2	posteriore de la constitución de	1104	
3	***********************	1099	
4	***************************************	1111	*
5		1111	*
6	ACTUAL CONTRACTOR CONT	1029	
7	***************************************	1118	*
8	management and the second	1122	*
9	ADDRESS CONTRACTOR CON	1117	*
10	mannamana	1116	*
11	uminimuminamum	1115	*
12	months and the contract of the	1114	٠
13	***************************************	1115	*
14	******************************	274	
15	telescontenes and the contract of the contract	0	
16	***************************************	0	
17	mentalitical managements	0	
18	ADDRESS CONTRACTOR OF THE PARTY	0	
19	Minimum	0	
20	***************************************	0	
21	***************************************	0	
22	resease and a second	544	
23	CONTROLLARDISEASCHE SEE SEE SEE	1107	*
24	***************************	1105	*
25	ALTERNATION AND ADDRESS OF THE PARTY OF THE	1104	
26	Manufalana and American	1107	*
27	emperoration description	1112	*
28	***************************************	1105	*
29	***************************************	1108	*
30	n-manual manual	1105	*
31	***************************************	1106	W

^{*} MDC CAN BE EXCEEDED UNDER OPTIMAL CONDITIONS

UNIT SHUTDOWNS AND POWER REDUCTIONS

UNIT NAME: VEGP UNIT 1

DOCKET NO. 50-424

DATE: JUNE 5, 1992

COMPLETED BY: G. L. HOOPER

TELEPHONE: (706) 826-4104

REPORT MONTH

MAY 1992

NO.	DATE	TYPE	DURATION (HOURS)	REASOZ	METHOD	LICENSEE EVENT REPORT NUMBER	SYSOODE	COMPONENT CODE (SUBCODE)	CAUSE & CORRECTIVE ACTION TO PREVENT RECURPENCE
92-2	5/14	F	190.2	D	1	1-92-4	AB	PSF	SEE BELOW

F: FORCED

REASON:

S: SCHEDULED A-EQUIPMENT FAILURE (EXPLAIN) 1 - MANUAL

B-MAINTENANCE OR TEST

C-REFUELING

D-REGULATORY RESTRICTION

E-OPERATOR TRAINING & LICENSE 5 - LOAD REDUCTION

F-ADMINISTRATIVE

G-OPERATIONAL ERROR (EXPLAIN)

H-OTHER (EXPLAIN)

METHOD:

3 - AUTO, SCRAM

9 - OTHER (EXPLAIN)

EVENTS REPORTED INVOLVE

A GREATER THAN 20% 2 - MANUAL SCRAM REDUCTION IN AVERAGE

DAILY POWER LEVEL FOR

4 - CONTINUATIONS THE PRECEDING 24 HOURS.

EVENT 92-2

CAUSE: THE UNIT WAS BROUGHT TO MODE 5 DUE TO UNIDENTIFIED RCS LEAKAGE OVER THE TECH SPEC LIMIT. THE LEAK WAS APPARENTLY CAUSED BY FATIGUE FAILURE IN A 1° WELDOLET WHICH CONNECTED A DOUBLE ISOLATION DRAIN VALVE TO A 6' SAFETY INJECTION SYSTEM PIPE.

CORRECTIVE ACTIONS: THE APPARENT CAUSE OF THIS EVENT WAS FATIGUE FAILURE WHICH INITIATED A CRACK IN THE WELD. THE VALVE ASSEMBLY WAS REMOVED AND THE WELDOLET WAS PLUGGED.

ENCLOSURE 2

VOGTLE ELECTRIC GENERATING PLANT - UNIT 2 MONTHLY OPERATING REPORT FOR MAY 1992

TABLE OF CONTENTS

NARRATIVE REPORT	Page V2	- 1
OPERATING DATA REPORT	Page V2	2
AVERAGE DAILY POWER LEVEL	Page V2	3
UNIT SHUTDOWNS AND POWER REDUCTIONS	Page V2	4

NARRATIVE REPORT

DOCKET NO. 50-425
DATE: JUNE 5, 1992
COMPLETED BY: G. L. HOOPER
TELEPHONE: (706) 826-4104

MAY 01 00:00 UNIT 2 IN MODE 5. REPAIR OF RCP IN PROGRESS. MAY 05 23:55 UNIT 2 ENTERED MODE 4. MAY 06 05:14 UNIT 2 ENTERED MODE 3. MAY 06 20:58 UNIT 2 ENTERED MODE 2. MAY 07 02:33 UNIT 2 REACTOR CRITICAL. MAY 08 04:01 UNIT 2 MODE 1. MAY DB 13:51 UNIT 2 GENERATOR TIED TO GRID. MAY 08 15:11 UNIT 2 TURBINE/GENERATOR TRIP FROM 25% DUE TO HIGH MSR LEVEL. MAY 09 03:33 UNIT 2 GENERATOR TIED TO GRID. MAY 10 02:04 UNIT 2 TURBINE/GENERATOR TRIP FOR TURBINE TRIP TESTING. MAY 10 05:22 UNIT 2 GENERATOR TIED TO GRID. MAY 14 13:47 UNIT 2 TURBINE/REACTOR TRIP DUE TO GENERATOR CONTROL POWER LOSS. MAY 15 00:19 UNIT 2 ENTERED MODE 2. MAY 15 01:40 UNIT 2 REACTOR CRITICAL. MAY 15 11:41 UNIT 2 MODE 1. MAY 15 13:42 UNIT 2 GENERATOR TIED TO GRID. MAY 18 04:00 UNIT 2 REACHED 100% POWER.

MAY 27 17:52 UNIT 2 BEGAN DERATE TO 90% DUE TO OPTR CALIBRATION.

MAY 31 23:59 UNIT 2 AT 100% POWER WITH NO OPERATIONAL PROBLEMS.

MAY 28 23:59 UNIT 2 RETURNED TO 100% POWER.

OPERATING DATA REPORT

DOCKET NO. 50-425

DATE: JUNE 5, 1992

COMPLETED BY: G. L. HOOPER

TELEPHONE: (706) 826-4104

OPERATING STATUS

1. UNIT NAME:	VEGP UNIT 2
2. REPORT PERIOD:	MAY 1992
3. LICENSED THERMAL POWER (MWI):	3411
4. NAMEPLATE RATING (GROSS MWe):	1215
5. DESIGN ELECTRICAL RATING (NET MWe):	1101
6. MAXIMUM DEPENDABLE CAPACITY (GROSS MWe):	1163
7. MAXIMUM DEPENDABLE CAPACITY (NET MWe):	1109
8. IF CHANGES OCCUR IN CAPACITY RATINGS	N/A
(ITEMS 3 THROUGH 7) SINCE LAST REPORT, GIVE REASONS:	

9. POWER LEVEL TO WHICH RESTRICTED, IF ANY (NET MWe):

NO RESTRICTIONS

10. REASONS FOR RESTRICTION, IF ANY:

N/A

	THIS MONTH	YR. TO DATE	CUMULATIVE
11. HOURS IN REPORTING PERIOD:	744	3647	26592
12. NUMBER OF HOURS REACTOR WAS CRITICAL:	585.6	2238.0	23230.4
13. REACTOR RESERVE SHUTDOWN HOURS:	0.0	0.0	0.0
14. HOURS GENERATOR ON-LINE:	522.5	2175.0	22786.4
15. UNIT RESERVE SHUTDOWN HOURS:	0.0	0.0	0.0
16. GROSS THERMAL ENERGY GENERATED (MWH):	1578601	7018278	73478046.0
17. GROSS ELEC. ENERGY GENERATED (MWH):	522352	2386278	24793429
18. NET ELEC. ENERGY GENERATED (MWH):	487462	2243368	23542899
19. REACTOR SERVICE FACTOR	78.7%	61.4%	87.4%
26. REACTOR AVAILABILITY FACTOR	78.7%	61.4%	87.4%
21. UNIT SERVICE FACTOR:	70.2%	59.6%	85.7%
22. UNIT AVAILABILITY FACTOR:	70.2%	59.6%	85.7%
23. UNIT CAPACITY FACTOR (USING MDC NET):	59.1%	55.5%	80.5%
24. UNIT CAPACITY FACTOR (USING DER NET):	59.5%	55.9%	80.4%
25. UNIT FORCED OUTAGE RATE:	6.5%	2.9%	2.3%
THE RESERVE OF THE PARTY OF THE	CAR SECURE IN A SECURE AND IN	BUT LINE AND DESCRIPTION OF THE RES	NA 45

26. SHUTDOWNS SCHEDULED OVER THE NEXT 6 MONTHS (TYPE, DATE, AND DURATION OF EACH):

NONE

27. IF SHUTDOWN AT END OF REPORT PERIOD, ESTIMATED DATE OF STARTUP: NA

DOCKET NO. 50-425
DATE: JUNE 5, 1992
COMPLETED BY: G. L. HOOPER
TELEPHONE: (706) 826-4104

DAY		Net MW
1	kiria mariter-derimina marita marita	0
2	Literary and the section of the sect	0
3	SCHOOLSHIP CORPARISHED AND ADDRESS	0
4	APO-MICHAELEMAN AND AND AND AND AND AND AND AND AND A	0
5	trimmintramiscomunic	0
6	nichtenteritenmannennerer	0
7	***************************************	0
8	RESCRIPT SCHOOL MARKET AND ADDRESS	0
9	income within the	141
10	mages, some manufacture	239
11	anness and the second	602
12	TAXABLE PARAMETERS AND ADDRESS OF THE PARAMETERS AND ADDRESS OF TH	749
13	amountmental and a second	902
14	anumer moneymore	526
15	stational and the state of the	174
16	theretone continues in the continues of	839
17	isotamuranounistavanos:	1043
18	discontinuoni mantani	1085
19	anameronamina.	1084
20	, maintenantenantenantena	1090
21	**************************************	1094
22	NACOTORNOCOM SEASON SEA	1109 *
23		1112 *
24	Hamming and St.	1107
25	S manufacture manufacture	1105
26		1107
27	***************************************	1070
28	3	1046
29		1111 *
30)	1108
3	1	1109 *

UNIT SHUTDOWNS AND POWER REDUCTIONS

UNIT NAME:

VEGP UNIT 2

DOCKET NO. 50-425

DATE: JUNE 5, 1992

COMPLETED BY: G. L. HOOPER

TELEPHONE:

(706) 826-4104

REPOR	RT MON	ГН	MAY 1992				, ,		
NO.	DATE	TYPE	DURATION (HOURS)	REASOZ	METHOD	LICENSEE EVENT REPORT NUMBER	S Y SC TO ED ME	COMPONENT CODE (SUBCODE)	CAUSE & CORRECTIVE ACTION TO PREVENT RECURRENCE
92-2 92-3 92-4 92-5	3/11 5/08 5/10 5/14	8 + 8 +	181.9 12.4 3.3 23.9	CABG	4 9 9 3	NA NA NA 2-92-10	ZZ SN TA TL	ZZZZZZ	SEE BELOW SEE BELOW SEE BELOW
F: FORCEI S: SCHED	D	REAS A-EC B-M C-RE D-RE E-OI F-AC	ON: QUIPMENT FA AINTENANCE EFUELING	ILUF OR T REST VININ	RE (E TEST TRICTIG &	XPLAIN) TON LICENSE	METH 1 - M 2 - M 3 - A 4 - C 5 - L	OD: ANUAL SCRAM UTO. SCRAM ONTINUATIONS DAD REDUCTION THER (EXPLAIN)	EVENTS REPORTED INVOLVE A GREATER THAN 20% REDUCTION IN AVERAGE DAILY POWER LEVEL FOR THE PRECEDING 24 HOURS.

EVENT 92-2

CAUSE: SCHEDULED REFUELING OUTAGE

H-OTHER (EXPLAIN)

CORRECTIVE ACTION: NO MAJOR SAFETY RELATED CORRECTIVE MAINTENANCE WAS PERFORMED.

CRITICAL PATH WAS:

RCP MOTOR REPAIR, PREPARE FOR MODE 2 ENTRY, MODE 1 ENTRY, TURBINE TESTING, BREAKER CLOSURE

EVENT 92-3

CAUSE: UNPLANNED AUTOMATIC TURBINE TRIP BELOW P-9 CAUSED BY HIGH MSR WATER LEVEL. THERE WERE TWO CAUSES OF THE HIGH WATER LEVEL; A COCKED PISTON ALIGNMENT ON 2-LV-4333, THE *A* HDT HIGH LEVEL DUMP VALVE, AND A STICKING CONTROLLER ON 2-LV-4363, THE MSDT DUMP VALVE, WHICH CAUSED IT NOT TO OPEN WHEN NEEDED.

CORRECTIVE ACTION: VERIFY TORQUE ON ALL HDT DUMP VALVE ACTUATOR PISTON BOLTS ON UNITS 1 AND 2. REVISE MAINTENANCE PROCEDURES TO APPLY LOCTITE TO THE THREADS OF THE PISTON BOLTS.

EVENT 92-4

CAUSE: PLANNED TURBINE TRIP BELOW P-9 FOR TURBINE TESTING.

CORRECTIVE ACTION: TESTING COMPLETED GENERATOR AGAIN TIED TO GRID.

EVENT 92-5

CAUSE: AUTOMATIC TURBINE TRIP/ REACTOR TRIP CAUSED BY THE GROUNDING OF THE DC POWER SUPPLY FOR THE GENEREX CIRCUITS DURING GENERATOR TESTING. THE LOSS OF CONTROL POWER STARTED A TRIP LOGIC SEQUENCE WHICH CAUSED A TURBINE TRIP/PEACTOR TRIP.

CORRECTIVE ACTION: FUTURE TESTING WILL UTILIZE FULLY INSULATED TEST LEADS. THE CUBICLES WILL BE CLEARLY LABELED AS A TRIP HAZARD. FUTURE OUTAGE SCHEDULES WILL RECOMMEND COMPLETION OF GENERATOR TESTING PRIOR TO 50% POWER.

ENCLOSURE 3

VOGTLE ELECTRIC GENERATING PLANT - UNITS 1 AND 2 MONTHLY OPERATING REPORT FOR MAY 1992

CHALLENGES TO PORV OR SAFETY VALVES

(ENCLOSURE 3)

VEGP UNITS 1 & 2

DOCKET NOS. 50-424,50-425 DATE: JUNE 5, 1992 COMPLETED BY: G. L. HOOPER TELEPHONE: (706) 826-4104

DATE	TAG NO.	EVENT TYPE	DESCRIPTION	
			NO EVENTS FOR MAY	