PRP MISSISSIPPI POWER & LIGHT COMPANY Helping Build Mississippi O. BOX 1640, JACKSON, MISSISSIPPI 39205 August 31, 1984 NUCLEAR LICENSING & SAFETY DEPARTMENT U.S. Nuclear Regulatory Commission Region II 101 Marietta St., N.W., Suite 2900 Atlanta, Georgia 30323 Attention: Mr. J. P. O'Reilly, Regional Administrator Dear Mr. O'Reilly: SUBJECT: Grand Gulf Nuclear Station Unit 1 Docket No. 50-416 License No. NPF-13 File: 0260/L-835.0 Special Report 84-033/0, Breach of Fire-Rated Penetration Seal AECM-84/0434

On August 1, 1984, a fire-rated wall penetration seal between the RHR "B" piping room and the RWCU "B" pump room was broken so that planned maintenance work could be performed. A fire watch was established as specified by Technical Specification 3.7.7.

The penetration will be resealed when the work is complete. This Special Report is submitted in accordance with Technical Specification 6.9.2 due to the LCO exceeding the seven-day time limit.

Yours truly,

Sam H Athle L. F. Dale Director

EBS/SHH:rg

109240092 840831

cc: Mr. J. B. Richard Mr. R. B. McGehee Mr. N. S. Reynolds Mr. G. B. Taylor

> Mr. Richard C. DeYoung, Director Office of Inspection & Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

> Document Control Desk U. S. Nuclear Regulatory Commission Washington, D. C. 20555

MENCIAL COPY

*1ember Midd

*1ember Middle South Utilities System

IE 25110