

CP&L

34 SEP 10 1984
Carolina Power & Light Company

P. O. Box 165, New Hill, North Carolina 27562
August 31, 1984

FILE: SH N-2/18
Item 180

MQAH 84-356

Mr. James P. O'Reilly
United States Nuclear Regulatory Commission
Region II
Suite 2900
101 Marietta Street, NW
Atlanta, Georgia 30323

SHEARON HARRIS NUCLEAR POWER PLANT, UNIT NO. 1
DOCKET NO. 50-400
RAB EMERGENCY AIR CLEANING UNITS - WELD DEFICIENCIES

Dear Mr. O'Reilly:


This is to confirm the August 30, 1984 telephone conversation between Mr. N. J. Chiangi (CP&L) and Mr. A. Hardin. Mr. Hardin was informed that the June 28, 1984 potentially reportable item, pertaining to the weld deficiencies identified in the RAB Emergency Air Cleaning Units supplied by CTI Nuclear, Inc., has been evaluated and considered not to be reportable per the provisions of 10CFR50.55(e) and 10CFR, Part 21.

Thank you for your consideration in this matter.

Yours very truly,

NJC/mt

cc: Mr. R. C. DeYoung
Mr. G. Maxwell
Mr. R. L. Prevatte


N. J. Chiangi - Manager
Quality Assurance/Quality Control
Harris Plant

8409240215 840831
PDR ADOCK 05000400
S PDR

110
OFFICIAL COPY
TE 27