

ENCLOSURE 1

NOTICE OF VIOLATION

Virginia Electric and Power Company  
North Anna

Docket Nos. 50-338 and 50-339  
License Nos. NPF-4 and NPF-7

The following violation was identified during an inspection conducted on April 6 - May 5, 1984. The Severity Levels were assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

Technical Specification 6.8.1.c requires, in part, that written procedures be established covering surveillance and test activities of safety-related equipment. ANSI N18.7-1976, to which the licensee is committed, requires that procedures incorporate or reference requirements and acceptance limits.

Contrary to the above, 1 and 2 PT 36.7.5 "Engineered Safeguard Features Pump Response Times" and numerous other time response testing periodic tests do not contain adequate acceptance criteria in that the acceptance criteria of these procedures do not specify acceptance limits.

This is a Severity Level IV violation (Supplement I).

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violation; (2) the reasons for the violation if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: JUN 11 1984