

DMB

U-0732
0982-L
L08(IEB83-06)-84(09-14)-L

ILLINOIS POWER COMPANY



CLINTON POWER STATION, P.O. BOX 678, CLINTON, ILLINOIS 61727

Docket No. 50-461

September 14, 1984

Mr. James G. Keppler
Regional Administrator
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Subject: Clinton Power Station Unit 1
IE Bulletin No. 83-06

Dear Mr. Keppler:

This interim report is an update in response to the subject IE Bulletin addressing the use of nonconforming materials supplied by Tube-Line Corporation. Previous Illinois Power reports on this subject were supplied to you via letters from Mr. D. P. Hall to Mr. J. G. Keppler dated December 23, 1983 and May 4, 1984. These reports provided Illinois Power's plan for identifying, locating and dispositioning Tube-Line Corporation materials supplied to the Clinton Power Station (CPS).

To date, Tube-Line materials supplied to CPS have been identified and 64% of these materials have been located. Review of safety related construction travelers to locate the remaining materials is continuing. Nonconformance reports (NCRs) are being issued and dispositioned as materials are located and the nonconforming materials are being returned to the vendors.

Illinois Power will provide your office with an interim report on resolution of IE Bulletin No. 83-06 in ninety (90) days.

Please notify us if you have any questions concerning this matter. I hereby affirm that the information in this letter is correct to the best of my knowledge.

Sincerely yours,

D. P. Hall
Vice President

KAB:lm

cc: B. L. Siegel, NRC Clinton Licensing Project Manager
NRC Resident Office
NRC Document Control Desk, Washington, D.C. 20555
Illinois Department of Nuclear Safety

8409250206 840914
PDR ADDCK 05000461
G PDR

1/0 I E 11
SEP 20 1984