## The second second

## UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION IV

611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-8064

SEP 22 1995

Southern California Edison Co.
San Onofre Nuclear Generating Station
ATTN: Harold B. Ray
Executive Vice President
P.O. Box 128
San Clemente, California 92674-0128

SUBJECT: NRC INSPECTION REPORT 50-361/95-16; 50-362/95-16

This refers to the inspection conducted by J. A. Sloan and others of this office on July 16 through August 26, 1995, at the San Onofre Nuclear Generating Station, Units 2 and 3. The purpose of the inspection was to determine whether activities authorized by the license were conducted safely and in accordance with NRC requirements. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress. The results of this inspection are documented in the enclosed report.

A significant weakness was noted in the control of maintenance work during the current Unit 3 refueling outage. Of particular concern were numerous discrepancies involving improper performance of procedure verification activities. Specific examples, noted in the enclosed inspection report, include failures to perform required verification signoffs, and improper verification signatures for work that had not been done, or work that had not been done in accordance with procedure requirements. Pending additional evaluation of the significance and scope of these problems, these items are considered unresolved, and will be reviewed in a future inspection.

This inspection included followup on Violation 361/9504-03, "Inadequate Corrective Actions Concerning Agastat Relays." After reviewing your response of July 11, 1995, and further reviewing the issue on site, we have determined that the safety significance of the repetitive relay failures was minor. The violation classification has been changed from Severity Level IV to noncited.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosures will be placed in the NRC Public Document Room.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

J. E. Dyer, Director
Division of Reactor Projects

Dockets: 50-361

50-362

Licenses: NPF-10

NPF-15

Enclosure:

NRC Inspection Report

50-361/95-16; 50-362/95-16

cc w/enclosure:

County of San Diego

ATTN: Chairman, Board of Supervisors

1600 Pacific Highway, Room 335 San Diego, California 92101

Rourke & Woodruff ATTN: Alan R. Watts, Esq.

701 S. Parker St. No. 7000

Orange, California 92668-4702

Public Utilities Department

City of Riverside

ATTN: Sherwin Harris, Resource

Project Manager

3900 Main Street

Riverside, California 92522

Southern California Edison Company San Onofre Nuclear Generating Station ATTN: R. W. Krieger, Vice President P.O. Box 128

San Clemente, California 92674-0128

California Department of Health Services
ATTN: Dr. Harvey Collins, Chief
Division of Drinking Water and
Environmental Management
P.O. Box 942732
Sacramento, California 94234-7320

San Diego Gas & Electric Company ATTN: Richard Krumvieda, Manager Nuclear Department P.O. Box 1831 San Diego, California 92112

Radiological Health Branch State Department of Health Services ATTN: Mr. Steve Hsu P.O. Box 942732 Sacramento, California 94234

City of San Clemente ATTN: Mayor 100 Avenida Presidio San Clemente, California 92672 E-Mail report to D. Nelson (DJN) E-Mail report to NRR Event Tracking System (IPAS)

bcc to DMB (IEO1)

bcc distrib. by RIV:

L. J. Callan DRSS-FIPB

Branch Chief (DRP/F, WCFO)

Senior Project Inspector (DRP/F, WCFO)

Branch Chief (DRP/TSS)

Leah Tremper (OC/LFDCB, MS: TWFN 9E10) M. Hammond (PAO, WCFO)

Resident Inspector

MIS System

RIV File

bcc w/o enclosures: M. Smith, WCFO

J. Bianchi, WCFO

DOCUMENT NAME: R:\ S023\S0516rp.JAS

To receive copy of document, indicate in box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

RIV:SRI:DRP\F	AC:DRP\F	D:DRP() E		
JAS1oan*	FRHuey*	JEDy or V		
09/08/95	09/11/95	09/22/95	09/ /95	09/ /95

\*previously concurred

OFFICIAL RECORD COPY

E-Mail report to D. Nelson (DJN) E-Mail report to NRR Event Tracking System (IPAS)

bcc to DMB (IEO1)

bcc distrib. by RIV:

L. J. Callan

DRSS-FIPB Branch Chief (DRP/F, WCFO)

Senior Project Inspector (DRP/F, WCFO) RIV File

Branch Chief (DRP/TSS)

Leah Tremper (OC/LFDCB, MS: TWFN 9E10) M. Hammond (PAO, WCFO)

Resident Inspector

MIS System

bcc w/o enclosures: M. Smith, WCFO J. Bianchi, WCFO

DOCUMENT NAME: R:\ S023\S0516rp.JAS

To receive copy of document, indicate in box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

RIV: SRI: DRP\F	AC:DRP\F	JEDY FOR		
JAS1oan*	FRHuey*	JEDy of De		
09/08/95	09/11/95	09/22/95	09/ /95	09/ /95

\*previously concurred

OFFICIAL RECORD COPY