

SEP 20 1984

MEMORANDUM FOR: R. L. Spessard, Director  
 Division of Project and Resident  
 Programs

FROM: Gary G. Zech, Chief  
 Vendor Program Branch  
 Division of Quality Assurance,  
 Safeguards and Inspection Programs  
 Office of Inspection and Enforcement

SUBJECT: POTENTIAL DEFICIENCY IN TENSILE STRENGTH  
 OF RIDGED STRUT PINS MANUFACTURED BY  
 ELCEN CORPORATION AND FURNISHED FOR USE  
 ON LASALLE, BRAIDWOOD AND BYRON NUCLEAR  
 FACILITIES

The above item is being closed without action based on Commonwealth Edison Company's (CE Co.) final report dated January 21, 1983, to J. G. Keppler, which indicates that testing conducted by CE Co. verified there is no significant safety problem associated with the subject pins.

If you have any questions concerning this matter please contact Mr. R. E. Oller (8-492-9634) of my staff.

Sincerely,  
 ORIGINAL SIGNED BY:  
 GARY G. ZECH

Gary G. Zech, Chief  
 Vendor Program Branch  
 Division of Quality Assurance  
 Safeguards, and Inspection Programs  
 Office of Inspection and Enforcement

DISTRIBUTION  
 R. Oller, IE  
 E. Merschoff, IE  
 G. Zech, IE  
 J. Partlow, IE  
 J. Taylor, IE  
 DMB-IE:09  
 VPB Reading

*FOR*  
 VPB/QASIP/IE  
 ROller  
 9/18/84

*EM*  
 VPB/IE  
 EMerschoff  
 9/18/84

*GZ*  
 VPB/IE  
 GZech  
 9/18/84

50-373, 374, 454, 455, 456, 457

8409270238 840920  
 PDR ADOCK 05000373  
 S PDR

ZE09