
·B.Grimes



Fermi 2 6400 North Dixie Highway Newport, Michigan 48166 (313) 586-4000





October 2, 1995 NRC-95-0103

Rules Review and Directives Branch U. S. Nuclear Regulatory Commission Washington, D. C. 20555

References:

- 1) Fermi 2 NRC Docket No. 50-341 NRC License No. NPF-43
- Proposed NRC Bulletin, "Potential Plugging of Emergency Core Cooling Suction Strainers for Debris in Boiling Water Reactors," and Draft Regulatory Guide, DG-1038, "Water Sources for Long-Term Recirculation Cooling Following Loss-of-Coolant Accident," 60 FR 39021, dated July 31, 1995

Subject:

Detroit Edison Comments on the Proposed NRC Bulletin and Draft Regulatory Guide on Potential Plugging of ECCS Suction Strainers

The purpose of this letter is to endorse the BWR Owners' Group comments on Reference 2, and specifically support the following points made in that response:

- The bulletin should specifically include the option of justifying the operability
 of currently installed passive strainers (possibly in combination with use of
 mostly reflective metallic insulation).
- The implementation date needs to be revised and extended, if modifications
 are shown to be necessary, to the second refueling outage after the final
 bulletin response is due, as opposed to the 1997 date currently in the draft
 bulletin.

USNRC October 2, 1995 NRC-95-0103 Page 2

If you have any questions, please contact Mr. Girija S. Shukla at (313) 586-4270.

Sincerely,

Lynne S. Goodman

Director, Nuclear Licensing

cc: T. G. Colburn

H. J. Miller

M. P. Phillips

A. Vegel