



# SAFEGUARDS INFORMATION

UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION II  
101 MARIETTA STREET, N.W.  
ATLANTA, GEORGIA 30323

Report Nos.: 50-413/92-12 and 50-414/92-12

Licensee: Duke Power Company  
422 South Church Street  
Charlotte, NC 28242

Docket Nos.: 50-413 and 50-414

License Nos.: NPF-35  
and NPF-52

Facility Name: Catawba 1 and 2

Inspection Conducted: April 13-16, 1992

Inspector: William J. Tobin 5/15/92  
W. J. Tobin Senior Safeguards Inspector Date Signed

Approved by: D. R. McGuire 5/15/92  
D. R. McGuire, Chief Date Signed  
Safeguards Section  
Nuclear Material Safety and Safeguards Branch  
Division of Radiation Safety and Safeguards

## SUMMARY

### Scope:

This routine, unannounced inspection was conducted in the area of the Physical Security Program for Power Reactors. Specifically the following areas were inspected; Management Support, Audits, Plans (and procedures), Power Supply, Maintenance (and compensatory measures) Training, and Safeguard Event Logs.

### Results:

In the areas inspected violations were identified relative to; failure to log unsecured vital area doors (92-12-01) (Paragraph 3.E) and inadequate safeguards event log procedure (92-12-02) (Paragraph 3.E). An Unresolved Item relative to the licensee's Safeguards Event procedure omitting certain reportable events is being evaluated (92-12-03) (Paragraph 3.E).

Strengths were noted in the maintenance and training areas. Management and Audits appear to be adequate. Power supply to the security system appears to be as required. Overall, while a decline in performance is noted, the licensee continues to implement adequate protection of the site safety equipment.

920528C033 920519  
PDR ADOCK 05C00413  
G PDR

# SAFEGUARDS INFORMATION

Document transmitted herewith contains sensitive unclassified information. When separated from enclosures, the document is decontrolled.