


September 12, 1984 RBG- 18890 File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator U. S. Nuclear Regulatory Commission Region IV, Office of Inspection and Enforcement 611 R a Plaza Drive, Suite 1000 Arlington, Texas 76011



River Bend Station Unit 1 Docket No. 50-458 Interim Report/DR-160

An interim or final status report concerning transformer cable lead lugs supplied by Gould Brown-Boveri will be provided by October 18, 1984.

Sincerely,

J. E. Booker

Manager-Engineering, Nuclear Fuels & Licensing

River Bend Nuclear Group

L. A. England you

JEB/PJD/1p

Dear Mr. Collins:

cc: Director of Inspection & Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

NRC Resident Inspector-Site

8409270466 84091 PDR ADDCK 050004