# New Hampshire Yankee

Ted C. Feigenbaum
President and
Chief Executive Officer

NYN- 92069

May 29, 1992

<sup>11</sup>nited States Nuclear Regulatory Commission Washington, DC 20555

Attention:

Document Control Desk

References:

- (a) Facility Operating License No. NPF-86; Docket No. 50-443
- (b) New Hampshire Office of Emergency Management Letter, dated May 18, 1992, G. L. Iverson to R. P. Strome, FEMA, Region 1

Subject:

Transmittal of Revisions to the New Hampshire Radiological Emergency Response Plan (NHRERP) and Supporting Documents

Gentlemen:

By letter dated May 18, 1992 [Reference (b)], the New Hampshire Office of Emergency Management transmitted Revision 5.A of the New Hampshire Radiological Emergency Response Plan (NHRERP) to the Federal Emergency Management Agency. This letter transmits Revision 5.A of the NHRERP, Enclosure 1, to the NRC pursuant to the requirements of 10CFR50.4(b)(5).

The changes contained in this revision, which are denoted by vertical change bars located in the left hand margin, were generated by the following:

- Relocation of the state transportation staging area from the Rockingham County Complex to the Pease International Tradeport;
- Revision of the East Kirgston Radiological Emergency Response Plan based on community input;
- · Training, drill, and annual plan review comments;

To assist in your ... ew, Enclosure 2 provides a matic, which identifies the changes and the applicable plat. ... cedure sections in which they appear. Only those changes that are substantive in nature appear on these matrices. Minor editorial changes are not identified.

010000 9206010209 920529 PDR ADDCK 05000443 AOB

United States Nuclear Regulatory Commission
Attention: Document Control Desk

If you should have any questions regarding the above, please contact Mr. James M. Peschel, Regulatory Compliance Manager, at (603) 474-9521, extension 3772.

Very truly yours,

Ted C. Feigenbaum

Enclosures

ce: (w/o enclosures):

Mr. Thomas T. Martin Regional Administrator U.S. Nuclear Regulatory Commission Region 1 475 Allendale Road King of Prussia, PA 19406

Mr. Gordon Edison, Sr. Project Mgr. Project Directorate 1-3
Division of Reactor Projects
U.S. Nuclear Regulatory Commission
Washington, DC 20555

(with enclosures):

Mr. Ebe C. McCabe, Chief (2 copies) Emergency Preparedness Section U.S. Nuclear Regulatory Commission Region I 475 Allendale Road King of Prussia PA 19406

Mr. Noel Dudley NRC Resident Inspector P.O. Box 1149 Seabrook, NH 03874

Controlled Distribution Lists

ENCLOSURE 1 TO NYN-92069

# NEW HAMPSHIRE RADIOLOGICAL EMERGENCY RESPONSE PLAN REVISION 5.A

# CHANGE SUMMARY (POADMAP)

SOURCE OF COMMENT	e. Driil comment	I list for Drill comment	e. Drill comment	PHS Drill comment DPHS	to the Drill comment	and Plan review le IFO.	ging Plan review
CORRECTIVE ACTION	Added references to the procedure.	Added reference to the RCDC call list for vehicle requirements.	Added references to the procedure.	Revised procedure to direct the DPHS initiator not to wait for follow-up information before activating the DPHS response staff.	Added the IFO clerical notification to the IFO RHTA procedure.	Clarified the procedures re: radios and channels to be used enroute to the IFO	Revised State Transportation Staging Area procedures for operations from Pease.
ISSUE	Procedure did not reference the Protective Action Criteria in Volume 8. Section 6.	Prucedure should reference the RCDC call list for vehicle requirements.	Procedure did not reference the Protective Action Criteria in Volume 8, Section 6.	Procedur directs the DPLO initiator to obtain follow-up information from the Control Room before activating response staff.	DPHS IFO admin staff was not notified during the drill.	Communications procedures for the monitoring teams enroute to the IFO required clarification.	The State Transportation Staging Area was moved from 3ockingham County Complex to Pease.
AFFECTED	Volume 5, Sec. 1, Governor's Rep. Procedure	Volume 5, Sec. 8, EOC Resource Officer Procedure	Volume 6, Sec. 1, DPHS Director	Volume 6, Sec. 2, DPHS Initiator Procedure	Volume 6, Sec. 5, DPHS IFO RHTA Procedure	Volume 6, Sec. 10, Monitoring Team Procedure	Volume 7, Sec. 14, Rock. Cty. Procedures

### NEW HAMPSHIRE RADIOLOGICAL EMERGENCY RESPONSE PLAN REVISION 5.A

### CHANGE SUMMARY (ROADMAP)

AFFECTED SECTION	ISSUE	CORRECTIVE ACTION	SOURCE OF COMMENT
Volume 8, List of Forms	Form 300K showed wrong Rev. number.	Corrected the Rev. number.	Plan review
Volume 9, Sec. B2.4	Sample news releases contained inconsistent descriptions for Site Area Emergency.	Corrected descriptions.	Drill comment
Volume 22, East Kingston RERP	East Kingston RERP was not consistent with the NHRERP.	Revised the East Kingston RERP and procedures to make consistent with the NHRERP.	Plan review
Volume 23, Exeter RERP	List of Effective Pages showed wrong Rev. numbers for certain pages.	Corrected the Rev numbers.	Plan review
Volume 29, New Castle RERP	RERP was not clear who directs the emergency response organization when Selectmen are not available. RADEF procedures incorrectly referenced Form 300A.	Corrected the organization chart to conform with EMD procedures to show that EMD directs the organization in the absence of the Selectmen. Corrected RADEF procedures.	Drill comment
Volume 34, Rye RERP	Police Chief procedure incorrectly referenced Table 3.91.	Corrected reference to Table 3.71	Drill comment
Volume 35, Seabrook RERP	List of Effective Pages incorrectly referenced a deleted page.	Removed page reference from the LOEP.	Plan review

ENCLOSURE 2 TO NYN-92069

## STATE OF NEW HAMPSHIRE EXECUTIVE DEPARTMENT



Office of Emergency Management
State Office Park South
107 Pleasant Street
Concord, New Hampshire 03301
603/271-2231
1-800-852-3792
FAX 803-225-7341



May 18, 1992

Mr. Richard H. Strome, Regional Director Federal Emergency Management Agency 442 J.W. McCormack POCH Boston, Massachusetts 02109

RE: New Hampshire Radiological Emergency Response Plan Rev. 5.A

Dear Mr. Strome:

The New Hampshire Office of Emergency Management has completed an update of the New Hampshire Radiological Emergency Response Plan. This update includes the following:

- Revision of NMRERP, Volume 7, Section 14, State Transportation Staging Area procedures to account for relocation of the State Transportation Staging Area from the Rockingham County Complex to the Pease International Tradeport.
- Revision of NHRERP, Volume 22, East Kingston Radiological Emergency Response Plan.
- Miscellaneous changes to other sections of the NHRERP resulting from recent training, drill and annual plan review comments.

Because the changes incorporated into this update are relatively limited in scope, the NHRERP, Rev. 5.A, update is transmitted in the form of change pages. The change pages are accompanied by "Change Instructions" which identify the pages to be removed from the NHRERP and the Rev. 5.A replacement pages to be inserted.

The changes made in the NHRERP, Rev. 5.A, update are denoted by vertical revision bars in the left-hand margin. To facilitate your review, a roadmap of the NHRERP, Rev. 5.A changes is provided.

If you have questions or require further information, please do not hesitate to contact me.

Sincerely,

George L. Iverson

Director

GLI/sjp

Enclosures

### NEW HAMPSHIRE RADIOLOGICAL EMERGENCY RESPONSE PLAN REVISION 5.A

### CHANGE SUMMARY (ROADMAP)

AFFECTED SECTION	ISSUE	CORRECTIVE ACTION	SOURCE OF COMMENT
Volume 5, Sec. 1, Governor's Rep. Proc.	Procedure did not reference the Protective Action Criteria in Volume 8. Section 6.	Added references to the procedure.	Drill comment
Volume 5. Sec. 8, EOC Resource Off. procedure	Procedure should reference the RCDC call list for vehicle requirements.	Added reference to the Rockingham County Call List for vehicle requirements.	Drill comment
Volume 6, Sec. 1, DPHS Director	Procedure did reference the Protective Action Criteria in Volume 8, Section 6.	Added references to the procedure.	Drill comment
Volume 6, Sec. 2, DPHS Initiator procedure	Procedure directs the DPHS Initiator to obtain follow-up information from the Control Room before activating response staff.	Revised procedure to direct the DPHS Initiator not to wait for follow-up information before activating the DPHS response staff.	Drill comment
Volume 6, Sec. 5, DPHS IFO RHTA procedure	DPHS IFO admin staff was not notified during the drill.	Added the IFO clerical notification to the IFO RHTA procedure.	Drill comment
Volume 6, Sec. 10, Monitoring Team procedure	Communications procedures for the monitoring teams enroute to the IFO required clarification.	Clarified the procedures re: radios and channels to be used enroute to the IFO.	Plan review
Volume 7, Sec. 14, Rock. Cty. procedures	The State Transportation Staging Area was moved from Rockingham County Complex to Pease.	Revised State Transportation Staging Area ; ocedures for operations fic Pease.	Plan review

# NEW HAMPSHIRE RADIOLOGICAL EMERGENCY RESPONSE PLAN REVISION 5.A

### CHANGE SUMMARY (ROADMAP)

AFFECTED SECTION	ISSUE	CORRECTIVE ACTION	SOURCE OF COMMENT
Volume 8, List of Forms	Form 300K showed wrong Rev.	Corrected Rev. number	Plan review
Volume 9. Sec. B2.4.	Sample news releases contained inconsistent descriptions for Site Area Emergency.	Corrected descriptions	Drill comment
olume 22. ast Kingston	East Kingston RERP was not consistent with the NHRERP.	Revised the East Kingston RERP and procedures to make consistent with the NHRERP	Plan review
olume 23. xeter RERP	List of Effective Pages showed wrong Rev. numbers for certain pages.	Corrected the Rev. Lumbers	Plan review
Volume 29. New Castle KERP	RERP was not clear who directs the emergency response organization when Selectment are not available. RADEF procedures incorrectly referenced form 300A.	Corrected the organization chart to conform with EMD procedures to show that EMD directs the organization in the absense of the Selectmen. Corrected RADEF.	Drill comment
Volume 34, Rye RERP	Police Chief procedure incorrectly reference Table 3.9-	Corrected reference to Table 3.7-	Drill comment
Volume35, Seabrook RERP	List of Effective Pages incorrectly referenced a deleted page.	Removed page reference from the LOEP.	Plan review

ATTNIC DCC DESK NRC UFTSITE THE ATTACHED DOCUMENTS CIDENTIFIED BELOW)
REPRESENT A CHANGE TO YOUR CONTROLLED DOCUMENT FILES, PLEASE ENSURE THAT ALL
DOCUMENTS REFERENCED ARE ATTACHED. ACKNOWLEDGE RECEIPT OF THIS TRANSMITTAL BY
COMPLETING THE ENDORSEMENT BELOW AND RETURNING THIS TRANSMITTAL TO THE RAD BY
06/01/92. THIS WILL INDICATE THAT YOU HAVE RECEIVED THE ATTACHED CONTROLLED
DOCUMENTS AND PROCESSED THEM IN ACCORDANCE WITH NYRM CHAPTER 3. SECTION TO:
UNLESS DIRECTED OTHERWISE BELOW. DESTROY SUPERCEDED COPIES. SHOULD YOU WISH
TO RETAIN SUPERCEDED COPIES FOR RECORD PURPOSES, STAFF THEM INFORMATION ONLY.
SUP PURCHYORDER PROPOURENT IDENT. SHEET ID ISSUREY QUANTITY

# RECEIPT ACKNOWLEDGEMENT NOT REQUIRED

W. W. FORE PLANNING A STREETING THE LITT THICK IS

DORK COMPLETEDISTATUS CODE TA OR GREATER) REMOVE FACHAGE FROM DOS

# \* \* ECCEIPT BORNDALEDGEMENT

RECEIVED BY

BATE

STON AND RETURN THE TOP COPY TO.

RESORDS MANAGEMENT DEPARTMENT 02-85 TEAGROOM STATION F. O. BOX 300 SEABROOK NO 04879

NYRH TRANSMITTAL STREET NO. 94371