



**GPU Nuclear Corporation**  
Post Office Box 388  
Route 9 South  
Forked River, New Jersey 08731-0388  
609 971-4000  
Writer's Direct Dial Number:

September 21, 1984


Director  
Nuclear Reactor Regulation  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Dear Sir:

Subject: Oyster Creek Nuclear Generating Station  
Docket No. 50-219  
Isolation Condenser System Piping Cracked Welds -  
Repair and Failure Analysis

Pursuant to our meeting with members of your staff on August 29, 1984, revision no. 1 to Technical Data Report (TDR) No. 580 is attached for your review. Changes to TDR 580 are described in detail on page 1a of its text. The revision includes the additional information you had requested at our meeting.

Please contact Mr. Drew G. Holland of my staff at (609)971-4643 in the event that any comments or questions arise.

Very truly yours,  
  
Peter B. Fiedler  
Vice President and Director  
Oyster Creek

PBF/dam  
Attachment

cc: Dr. Thomas E. Murley, Administrator  
Region I  
U.S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, PA 19406

NRC Resident Inspector  
Oyster Creek Nuclear Generating Station  
Forked River, NJ 08731

8409280186 840921  
PDF. ADDCK 05000219  
S PDR

*Acc 11*