BOSTON EDISON COMPANY

BOD BOYLSTON STREET
BOSTON, MASSACHUSETYS 02199

WILLIAM D. HARRINGTON BENIDR VICE PRESIDENT NUCLEAR September 24, 1984 BECo 84-159

Mr. Domenic B. Vassallo, Chief Operating Reactors Branch #2 Division of Licensing Office of Nuclear Reactor Regulation U.S. Nuclear Regulatory Commission Washington, D.C. 20555

> License No. DPR-35 Docket No. 50-293

NUREG 0737, ITEM I.D.1: Detailed Control Room Design Review

Following the accident at Three Mile Island, the NRC requested that licensees conduct a detailed control room design review (DCRDR) to improve the ability of nuclear power plant control room operators to prevent or cope with accidents by improving the information provided to the operators.

By letter of October 26, 1983 Boston Edison Company (BECo) committed to perform such a review, and to provide a summary report by September 23, 1984 which would contain an implementation date.

The summary report accompanies this letter, and a variety of modifications are identified within it. While some of these modifications can be physically performed during power operation, the final implementation requires an operator-machine interface such that completion can be effected only after a refueling outage. This is to allow operator training and familiarization with the changes.

Because of this, the DCRDR modifications will be incorporated into BECo's Long Term Program, with completion occurring at the end of refueling outage #8. This schedule assumes issuance of a Safety Evaluation Report by NRC in accordance with the schedule for such provided in Generic Letter 82-33.

Should you wish further information on this report, please contact us.

Very truly yours,

Hannigton

PMK/ns

Attachment: Detailed Control Room Design Review Summary Report

cc: one copy to Mr. D. B. Vassallo ten copies to Mr. Paul Leech

> 8409280242 840924 PDR ADOCK 05000293 PDR

A003